

## REPORT DOCUMENTATION PAGE

READ INSTRUCTIONS  
BEFORE COMPLETING FORM

1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report Feeder Dam at Glens Falls Upper Hudson River Basin, Warren-Saratoga County, New York/ Inventory No. N.Y. 143		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) George Koch, P.E.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS New York State Department of Environmental Conservation/ 50 Wolf Road Albany, New York 12233		8. CONTRACT OR GRANT NUMBER(s) DACW-51-79-C-0001
11. CONTROLLING OFFICE NAME AND ADDRESS New York State Department of Environmental Con- servation/ 50 Wolf Road Albany, New York 12233		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS 12 298
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza/ New York District, CofE New York, New York 10007		12. REPORT DATE 10 July 1979
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) L E T T E R		
18. SUPPLEMENTARY NOTES National Dam Safety Program. Feeder Dam at Glens Falls (Inventory Number NY-143), Upper Hudson River Basin, Warren Saratoga County, New York. Phase I Inspection Report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety Feeder Dam at Glens Falls National Dam Safety Program Warren County Visual Inspection Saratoga County Hydrology, Structural Stability Hudson River		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. The Feeder Dam at Glens Falls did not reveal any conditions which would render the dam a hazard to life or property. A number of deficiencies were found which will require immediate attention.		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

393 970

JO

AD A 078044

DDC FILE COPY

AD A 078044

# UPPER HUDSON RIVER BASIN


## FEEDER DAM AT GLENS FALLS

WARREN - SARATOGA COUNTY

NEW YORK

INVENTORY NO. N.Y. 143

## PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM



DAC FILE COPY

APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED  
CONTRACT NO. DACW-51-79-C0001

NEW YORK DISTRICT CORPS OF ENGINEERS

FEBRUARY, 1979

79 2 10 011

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DTIC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probably Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.



PHASE 1 INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
FEEDER DAM @ GLENS FALLS  
I.D. No. NY-143  
(#378 - UH)  
UPPER HUDSON RIVER BASIN  
WARREN-SARATOGA COUNTIES, NEW YORK

TABLE OF CONTENTS

	<u>PAGE NO.</u>
- ASSESSMENT	
- OVERVIEW PHOTOGRAPH	
1 PROJECT INFORMATION	1
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	2
2 ENGINEERING DATA	7
2.1 DESIGN	7
2.2 CONSTRUCTION RECORDS	7
2.3 OPERATION RECORD	7
2.4 EVALUATION OF DATA	8
3 VISUAL INSPECTION	9
3.1 FINDINGS	9
3.2 EVALUATION OF OBSERVATIONS	11
4 OPERATION AND MAINTENANCE PROCEDURES	12
4.1 PROCEDURE	12
4.2 MAINTENANCE OF DAM	12
4.3 MAINTENANCE OF APPURTENANT STRUCTURES	12
4.4 WARNING SYSTEM IN EFFECT	12
4.5 EVALUATION	12

5	HYDROLOGIC/HYDRAULIC	13
5.1	DRAINAGE AREA CHARACTERISTICS	13
5.2	ANALYSIS CRITERIA	13
5.3	SPILLWAY CAPACITY	13
5.4	RESERVOIR CAPACITY	13
5.5	FLOODS OF RECORD	14
5.6	OVERTOPPING POTENTIAL	14
5.7	EVALUATION	14
6	STRUCTURAL STABILITY	15
6.1	EVALUATION OF STRUCTURAL STABILITY	15
7	ASSESSMENT/RECOMMENDATIONS	17
7.1	ASSESSMENT	17
7.2	RECOMMENDED MEASURES	17

APPENDIX

- A. PHOTOGRAPHS
- B. ENGINEERING DATA CHECKLIST
- C. VISUAL INSPECTION CHECKLIST
- D. HYDROLOGIC/HYDRAULIC ENGINEERING DATA AND COMPUTATIONS
- E. STRUCTURAL STABILITY COMPUTATIONS
- F. REFERENCES
- G. CORPS OF ENGINEERS GUIDELINES
- H. DRAWINGS

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Project	
Agency	
Load/or	
Dist	Special
AR3	
Q	

PHASE 1 REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam:	Feeder Dam @ Glens Falls I.D. No. NY-143 (#378 - UH)
State Located:	New York
County Located:	Warren - Saratoga
Watershed:	Upper Hudson River Basin
Stream:	Hudson River
Date of Inspection:	November 2, 1978

ASSESSMENT

Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property. However, significant deficiencies and deterioration was observed at one portion of the dam, the North Bulkhead, so as to warrant additional study and analysis as well as corrective action by maintenance forces. Such corrective action should be completed prior to the next period of anticipated high river flows (Spring 1980). All additional data gathering and investigations should be completed within one year of the date of this Phase 1 report and all remedial measures deemed necessary, based upon the findings of the investigations, should be completed within two years of the date of this report. During the interim period, a detailed emergency-operation plan and warning system should be developed and implemented.

The spillway capacity of the dam, although not having sufficient discharge capacity for passing one-half the Probable Maximum Flood (PMF), is considered to be inadequate. For such a large storm event, a high tailwater condition would result in the flooding of the downstream hazard areas. Hence, dam failure from overtopping would not significantly increase the hazard to loss of life downstream from that which would exist just before overtopping failure. In addition, the structural stability analysis performed for the spillway does not indicate unacceptable factors of safety for either overturning or sliding when subjected to the one-half PMF event.

Other deficiencies found during the visual inspection concerned concrete surface deterioration and cracking, non-operable or non-existent gate machinery, and an overall need for increased maintenance of the dam. Such deficiencies should be corrected and completed by maintenance forces within two years of the date of this report.

George Koch

George Koch  
Chief, Dam Safety Section  
New York State Department of  
Environmental Conservation  
NY License No. 45937


Approved By:

Clark H. Benn

Col. Clark H. Benn  
New York District Engineer

Date:

10 July 79



OVERVIEW

FEEDER DAM @ GLENS FALLS  
(Looking South)

PHASE 1 INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
FEEDER DAM @ GLENS FALLS  
I.D. No. NY-143  
(#378 - UH)  
UPPER HUDSON RIVER BASIN  
WARREN-SARATOGA COUNTIES, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase 1 inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.

b. Purpose of Inspection

This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, determine if they constitute hazards to life and property, and recommend remedial measures where necessary.

1.2 DESCRIPTION OF PROJECT

a. Description of the Dam and Appurtenant Structures

The Feeder Dam at Glens Falls is a concrete gravity dam having a 615 foot long ungated river spillway section with flashboards including a 20 foot wide inclined logway, a North Bulkhead adjacent to the spillway section, 114 feet long containing 6 vertical-lift gates; a Feeder Canal Intake Structure adjacent to the North Bulkhead, 64 feet wide containing a tainter gate and 2 vertical-lift sluice gates; a 65 foot long concrete abutment wall extending into the existing ground; a South Bulkhead adjacent to the spillway section, 151 feet long containing 8 vertical head gates; a 35 foot long concrete gravity abutment wall extending into the existing ground. A drawing showing the pertinent features at the dam is included in Appendix H.

An operating hydroelectric power station is located immediately Southeast of the spillway-South Bulkhead contact. The South Bulkhead gates control the inflow to the forebay of the power station. This power station houses 5 hydromachinery units which discharge into a river tailrace immediately downstream of the dam.

b. Location

The dam is located on the Hudson River, Southwest of the City of Glens Falls and approximately 0.8 miles Southeast of Interchange 18 of Interstate 87.

c. Size Classification

This dam is 36 feet high and impounds a reservoir of 6200 acre-feet. It is classified as an "intermediate" size dam (storage capacity between 1000 and 50,000 acre-feet).

d. Hazard Classification

The dam is classified "high" hazard because of the downstream populations located in South Glens Falls and the City of Glens Falls.

e. Ownership

The Feeder Dam at Glens Falls is owned by the State of New York, Department of Transportation (NYS-DOT), Waterways Maintenance Subdivision. It is located in DOT-Region One, whose headquarters are in Albany, New York.

Waterways Maintenance Subdivision

Region One

New York State-DOT  
Main Office - State Campus  
1220 Washington Avenue  
Albany, New York 12232

NYS - DOT  
84 Holland Avenue  
Albany, NY 12208

Director - Mr. Joseph Stellato  
(AC - 518) 457-4420

Waterways Maintenance:  
Engineer - Mr. John Hulchanski  
(AC - 518) 474-6715

f. Purpose of Dam

The primary purpose is for flow diversion into the Glens Falls Feeder Canal. This canal supplies the Champlain Barge Canal, at its summit located 5 miles downstream, with water for navigation. The dam provides a storage pool for the hydroelectric power station and it also functions as a flood control structure.

g. Design and Construction History

The original dam at this site was constructed prior to February 1870 as a straight-aligned crib structure extending across the entire river. Saw mill buildings existed near the present locations of the North Bulkhead and hydroelectric power station. A water-feed by-pass and navigation lock existed at the present location of the Feeder Canal Intake Structure. The existing concrete gravity dam with appurtenant structures was constructed in about the year 1913, and the former dam located just upstream was removed. Power station construction occurred in 1923.

h. Normal Operating Procedures

Water flows over the ungated spillway section. Flow diversions from the storage pool occur through the Feeder Canal Intake Structure and through the head gates in the South Bulkhead. The North Bulkhead gates are not operable.

1.3 PERTINENT DATA

a. Drainage Area

(square miles)  
2801

b. Discharges at Dam

(cfs)

See Page 3

		DISCHARGE				
STAGE	DESCRIPTION	SPILLWAY *	NORTH BULKHEAD GATES	FEEDER CANAL SLUICE GATES	SOUTH BULKHEAD GATES	(CFS) TOTAL
282.0	Spillway Crest	0	3436	104	12936	15936
283.5	Top-Bulkhead Gates	---	4800	186	15408	-----
284.9	Top-Flashboards	11055	7338	254	22272	40919
287.5	Top-Sluice Gates	---	----	334	-----	-----
290.0	Top of Dam	58029	10350	1178	28392	97949

\* without Flashboards

Hydroelectric power station machinery (5 units)

(cfs)  
5,000

Maximum recorded discharge (April 12, 1922)

56,876

c. Elevations (Barge Canal Datum - BCD)

Top of South Bulkhead	297.0
Top of Feeder Canal Intake Structure and North Abutment Wall.Existing ground @ North Abutment Wall	292.0

<u>Top of Dam</u>	
Top of North Bulkhead	290.0
Existing ground @ South Abutment Wall	

Top of Flashboards	284.9
--------------------	-------

Spillway Crest	282.0
Inclined Logway Crest	280.0
Feeder Canal Sluice Gates - bottom	279.5
North Bulkhead gates - bottom	276.0
South Bulkhead gates - bottom	270.0

Datum Conversion:

USGS 0.0 equals BCD 1.18

d. Reservoir

	Surface Area (acres)
Top of Dam	493
Top of Flashboards - Normal Pool	493
Spillway Crest	493
Logway Crest	493



<u>e. Storage Capacity (est.)</u>	(acre-feet)
Top of Dam	10100
Top of Flashboards	7600
Spillway Crest	6200
Logway Crest	5200

f. Dam

Type: Concrete gravity with  
appurtenant structures

Length:	(feet)
Spillway Crest	615
Inclined Logway	20

Height:	(feet)
Structural	36

Width @ Spillway Crest:	(feet)
Upstream radius	2
Downstream radius (ogee)	6

Width @ Logway Crest:	(feet)
Upstream radius	1
Total	3.5

g. Spillway

Type: Ungated, ogee-section, concrete  
gravity structure including an  
inclined logway and having wooden  
flashboard

Weir Length.	(feet)
Spillway Crest	615
Inclined Logway	20

Crest Elevation (BCD):

Spillway Crest	282.0
Logway Crest	280.0

h. Reservoir Drain

None

i. Appurtenant Structures

1) North Bulkhead:

6 vertical - lift gates with each opening  
(7.5' H x 14.92' W)

Control Machinery - inoperative

Length (feet)	114
Elevations (BCD):	
Top	290.0
Top of Gate Opening	283.5
Bottom of Gate Opening	276.0

2) Feeder Canal Intake Structure:

Entrance Control structures:

Tainter Gate - 15.8' W  
Needle Dam

Canal Discharge Control structures:

Two vertical - lift sluice gates with  
each opening (8' H x 6' W)

Width of entire Intake Structure:	(feet)
@ Entrance Control Structures	64
@ Discharge Control structures	50
@ Feeder Canal (channel)	40
Elevations (BCD):	
Top (wall)	292.0
Top of sluice gate opening	287.5
Bottom of sluice gate opening	279.5
Feeder Canal (channel) invert	275.0 (est.)

3) North Abutment Wall:

Concrete structure extending from the Feeder  
Canal Intake structure into the existing  
ground.

Length (feet)	65
Elevation (BCD):	Top 292.0

4) South Bulkhead:

8 vertical - lift gates with each opening  
(13.5' H x 15' W)  
Control machinery - non-existent

Length (feet)	151
Elevations (BCD):	
Top	297.0
Top of Gate Opening	283.5
Bottom of Gate Opening	270.0

5) South Abutment Wall:

Concrete gravity structure extending from the  
South Bulkhead into the existing ground.

Length (feet)	35
Elevation (BCD):	Top 290.0

6) Hydroelectric Power Station:

The forebay located directly downstream of the South Bulkhead leads to 5 hydromachinery units.

18 Bays - each opening (13.3' W) with trash racks

5 Hydromachinery units - each @ 1000 cfs capacity

Ice sluice located at the East end of the forebay; opening (6'± diameter concrete pipe)

Elevations (BCD):

Design High Water	290.0
Top of Trash Racks	288.0
Top of Flashboards - Normal Pool (Dam)	284.9
Minimum Water Surface	282.0
Design High Tailwater	281.0
Centerline of hydromachinery units	275.0
Design Low Tailwater	268.0
Bottom of Trash Racks	266.25
Bottom of hydromachinery units	251.5

## SECTION 2: ENGINEERING DATA

### 2.1 DESIGN

#### a. Geology

The Feeder Dam at Glens Falls is located in the Hudson Valley Lowlands physiographic province of New York State. Rock in this area was formed during the Ordovician period. The bedrock in these areas is predominantly limestone and dolostone. The present surficial soils have resulted primarily from glaciations during the Cenozoic Era; the Wisconsin glaciation being the most recent event to affect this area, having occurred approximately 11,000 years ago.

#### b. Subsurface Investigations

No records of any subsurface investigations were available. Based on the plans which were available for this structure, it appears that the structure is founded on bedrock.

#### c. Dam and Appurtenant Structures

The present dam was constructed about the year 1913; having replaced a crib structure which had been in existence prior to February 1870. The present structure was designed by the New York State Department of Public Works (now NYS-DOT). Drawings for the construction of the present dam (Contract No. 56, Champlain Canal - Section 2) are included in Appendix H).

Since the 1913 dam construction, major changes have been made on both ends of the structure. The NYS-DOT modified the Feeder Canal end of the dam by removing the bypass and navigation lock and installing a tainter gate and two sluice gates for flow control into the Canal channel. A drawing showing the modification is included in Appendix M. The hydroelectric power station was constructed adjoining the South Bulkhead in 1923. The station was designed by Mr. A.H. White, Chief Engineer for the Moreau Manufacturing Corporation. Drawings for this construction are included in Appendix H. Presently, the power station is operated by Niagara Mohawk Power Corporation, who also have ownership and maintenance responsibility for the flashboards existing on the spillway crest.

### 2.2 CONSTRUCTION RECORDS

No records were available regarding the construction of the dam. Correspondence concerning the construction of the power station was obtained from the files of the Department of Environmental Conservation.

### 2.3 OPERATION RECORD

The dam is visually inspected on an irregular basis by engineers from NYS-DOT. Mean daily water levels were recorded from 1916 to 1961 by NYS-DOT using a gauge located just upstream from the canal intake gates. These records are on file at the NYS-DOT Region One, Waterways Maintenance Office. Although the gauge still exists, no readings have been regularly recorded since 1961. Water surface levels in the power station forebay are monitored on an irregular basis.

2.4

EVALUATION OF DATA

The data presented in this report was obtained from the files of the Department of Environmental Conservation and the New York State Department of Transportation, plus conversations with Niagara Mohawk Power Corporation engineers. The information available appears to be adequate and reliable for Phase 1 inspection purposes.

## SECTION 3: VISUAL INSPECTION

### 3.1 FINDINGS

#### a. General

Visual inspection of the Feeder Dam at Glens Falls and the surrounding area was conducted on November 2, 1978. The weather was clear and sunny with the temperature near 45° F. The water surface elevation recorded from the gauge was 284.55.

#### b. Dam - Spillway

No flow was occurring over the spillway except for minor quantities resulting from wave action over the top of the flashboards. The horizontal and vertical alignment of the crest as well as the condition of the Spillway-North Bulkhead contact were satisfactory. The exposed concrete surface revealed deterioration over its entirety. The surface was rough and uneven, with holes and depressions resulting from the removal of concrete and aggregate. Two larger eroded depressions were observed on the Spillway section nearer the North Bulkhead.

The flashboards were relatively new with minor leakage in several locations occurring under the boards. The horizontal alignment of the flashboards was not straight; having three large bowed-out sections, two north of the logway and one south of it.

#### c. Appurtenant Structures

1) North Bulkhead: This structure was the most severely deteriorated portion of the entire dam. Deficiencies consisted of cracked concrete slabs, spalled and eroded concrete surfaces, reduced structural wall thicknesses, and leakage through concrete walls. For clarity, Bay 1 is that lift-gate section of the Bulkhead nearest the Feeder Canal Intake Structure and Bay 6 is nearest the Spillway.

The following deficiencies were observed:

- a) Leakage through the structural concrete vertical members, referred to as buttress walls, nearest the gates at Bays 3/4, (most severe), 1/2, and 1/abutment.
- b) Leakage at Bay 2 through the concrete overhang located directly behind the vertical plane of the gate.
- c) Leakage of the gates either around the periphery or through the wood itself or both at all 6 Bays.
- d) Deteriorated concrete buttress walls at the elevation of the gate bottom (276.0). The following table indicates the extent of deterioration from the original 30 inch thick walls:

Buttress Wall	Thickness Remaining	Concrete Loss
1/2	18"	12"
2/3	21"	9"
3/4	21"	9"
4/5	22"	8"
5/6	—	minor

- e) Concrete cracking entirely across and through the top slab spanning Bay 6.
- f) Structural cracking and vertical displacement at the Bay 6 concrete overhang - spillway abutment contact.
- g) Concrete cracking across the top slabs spanning all the Bays, primarily at mid-span and at each end of the span, and cracking between the anchor bolts for the existing gate machinery.
- h) Concrete deterioration of the bulkhead base slab (Elev. 271.0±) similar to the surface of the spillway.
- i) Concrete spalling of the top surface of the Bay 1 top slab.
- j) Non-operable gate machinery at Bays 2, 3, 6 and non-existent gate machinery at Bays 1, 4, and 5. The machinery present had steel welded to the gears to prevent movement of the gates.

The Spillway - Bay 6 abutment wall downstream of the Bulkhead was in satisfactory condition; revealing only minor spalling of the concrete surfaces.

2) Feeder Canal Intake Structure: Visual inspection of the concrete surfaces revealed only minor concrete surface spalling and cracking. The visible portions of the tainter gate and concrete needle dam were in satisfactory condition. It was not determined if the tainter gate is a fixed or moveable flow control device. The sluice gates were partially open and appeared to be functioning satisfactorily.

This Intake Structure transitions into the mortar-surfaced masonry walls of the canal (channel) near the outlets of the two sluice gates. Inspection of these masonry walls revealed concrete cracking and joint separation along both sides of the channel. Minor leakage from the canal was observed coming through the river-side wall at several locations downstream of the Intake Structure. Approximately 150 feet downstream and along this wall, there exists a 3.5 foot wide vertical sluice gate which also was leaking. Dumped stone-block rubble buttresses this outer channel wall.

3) North Abutment Wall: This concrete structure was in satisfactory condition. The top of this wall and the existing ground were at the same elevation with no indication of soil erosion.

4) South Bulkhead: This structure could not be closely inspected because of a locked fence barring access to the structure's top slab. However, minor concrete cracking and spalling was noticeable on both upstream and downstream vertical surfaces spanning the 8 gates. No in-place gate machinery existed for operating these head gates. However, flow through the gates into the forebay was occurring unimpeded.

5) South Abutment Wall: This concrete structure was in satisfactory condition. Some existing ground directly upstream of the wall had been eroded but this area extended only 10 feet or less back from the river's edge. The remainder of the existing ground was at the same elevation as the top of the wall.

6) Hydroelectric Power Station: This operating power station is under the regulatory control of the Federal Energy Regulatory Commission and is subject to their inspection criteria. Therefore, a detailed inspection of this structure was not made. However, visual observations of the areas at the forebay, ice sluice, and tailrace did not reveal any unusual conditions.

d. Reservoir

Trees and brush as well as open fields occur along the river's edge. There was no signs of soil instability in the reservoir area immediately upstream of the dam.

e. Downstream Channel

No unusual conditions were noticeable in the downstream Hudson River channel. Trees and brush grow to and along the edge of the river.

3.2

EVALUATION OF OBSERVATIONS

Visual observations of the dam (spillway) did not reveal any problems which would affect the immediate safety of the structure. The deficiencies observed can be corrected by increasing the maintenance effort expended on this particular part of the entire river structure.

Visual observations of the North Bulkhead did reveal conditions which could affect the integrity of the structure if allowed to deteriorate further. Specifically, leakage through the structural concrete buttress walls near the lift gates, concrete deterioration of the buttress walls themselves, and the structural cracking and vertical displacement at the Bay 6 - Spillway abutment contact are of particular concern.

Visual observations of the other appurtenances did not reveal conditions which would affect either their immediate safety or the safety of the dam. The deficiencies observed can be corrected during normal maintenance operations.



## SECTION 4: OPERATION AND MAINTENANCE PROCEDURES

### 4.1 PROCEDURE

Normal water surface is at or slightly above the top of the flashboards. Flow diversions occur through the Feeder Canal Intake Structure and through the South Bulkhead gates (a maximum diversion of 5000 cfs) for hydroelectric power generation.

### 4.2 MAINTENANCE OF DAM

Maintenance of the spillway portion of the dam has been minimal. Maintenance of the flashboards occurs annually and often times more frequently. Floating ice coming downriver during the early Spring removes sections of the flashboards, thereby requiring replacement and continuing maintenance. Fifty percent replacement is not uncommon and during the last few years, nearly entire replacement has been necessary.

### 4.3 MAINTENANCE OF APPURTENANT STRUCTURES

Maintenance of all of the appurtenant structures excluding the power station has also been minimal. However, the North Bulkhead structural member concrete deterioration and leakage problems requires more immediate attention. Maintenance of the lift-gate machinery has been minimal. The Intake Structure sluice gates are operational for regulating the Feeder Canal channel inflows. However, the tainter gate and needle dam operation is unknown although they appeared to be functioning properly. The head gates at the South Bulkhead controlling inflow to the forebay also appeared to be functioning properly.

### 4.4 WARNING SYSTEM IN EFFECT

No apparent warning system is present.

### 4.5 EVALUATION

Operation of the flow control sluice gates and head gates appears satisfactory. Maintenance of the flashboards is also satisfactory. Increased maintenance is required for the entire dam with primary emphasis placed on the entire North Bulkhead structure, including the structural concrete members, buttress walls, gates, and gate machinery. In addition, all masonry and concrete surfaces should be repaired as necessary.

## SECTION 5: HYDROLOGIC/HYDRAULIC

### 5.1 DRAINAGE AREA CHARACTERISTICS

The delineation of the contributing watershed to this dam is shown on the map titled "Drainage Area - Feeder Dam @ Glens Falls" (Appendix D). With the drainage area encompassing some 2801 square miles, the Hudson River main stem travels approximately 100 miles from its headwaters south of Lake Placid to the Feeder Dam site. Major tributaries to the Hudson River are the Cedar, Indian, Boreas, Schroon, and Sacandaga Rivers. Numerous lakes including Brant, Schroon, and Piseco lie within the basin as well as two major reservoirs; Indian Lake and the Sacandaga Reservoir. Over three-fourths of the basin lies within the Adirondack Mountain area where elevations rise to +5344 at Mount Marcy. Elevations of the existing ground at the Feeder Canal Intake Structure are near +290. Large areas of developed land relative to the size of the drainage basin are minimal, the largest municipality being Warrensburg.

### 5.2 ANALYSIS CRITERIA

No hydrologic/hydraulic information was available regarding the original design for this dam. Therefore, the analysis of the spillway capacity of the dam was performed using streamflow gaging station records (Appendix D) and data contained in a Corps of Engineers report entitled "Upper Hudson and Mohawk River Basins Hydrologic Flood Routing Models". The methodology described in this report employed the Corps of Engineers HEC-1 computer program in developing a model that correlated well with past known major storm events; i.e., the storms of October 1945, December 1948, and June 1972. No direct computer analysis using HEC-1 was performed. The spillway design flood selected for analysis was the PMF (Probable Maximum Flood) in accordance with recommended guidelines of the U.S. Army Corps of Engineers.

### 5.3 SPILLWAY CAPACITY

The single, concrete gravity, ogee spillway with the flashboards acts as the dam in forming the reservoir pool for the Feeder Canal Intake Structure and the hydroelectric power station. The 615 foot long overflow section includes an inclined logway, 20 feet long, that is located 175 feet from the North Bulkhead.

Discharges for the weirs and gates were computed using both weir and orifice flow relationships for the representative water surface elevations analyzed. The flashboards are designed for failure when the head reaches 1.5 to 2.0 feet above the top of the boards. Hence, all of the analyses performed assumes no flashboards exist. Maximum discharges through the hydroelectric power station existing machinery (5 units) was determined to be 5,000 cfs.

The spillway does not have sufficient capacity for discharging the peak outflow from one-half the PMF. For this storm event, the peak inflow and peak outflow is 149,500 cfs, whereas the PMF peak discharge is 299,000 cfs. The computed spillway capacity is 58,029 cfs.

### 5.4 RESERVOIR CAPACITY

The normal water surface is at or slightly above the top of the flashboards. Storage capacity for that water surface elevation is 7600 acre-feet. Without the flashboards, the storage capacity at the spillway crest is 6200 acre-feet. Storage capacity at the logway crest is 5200 acre-feet.

The total storage capacity to the top of dam (elevation 290.0) is 10,100 acre-feet. The limit of the reservoir pool is at Sherman Island power station and diversion dam, located approximately 6.8 river miles upstream.

#### 5.5 FLOODS OF RECORD

The maximum known discharge on the Hudson River was recorded upstream at the Spier Falls Dam on March 28, 1913 when a flow of 89,100 cfs was measured. The present Feeder Dam was under construction at the time and newspaper articles for the period indicate the dam site was flooded and only a small cofferdam washed out. The main cofferdam remained solid and withstood the floodwaters. The maximum recorded (gaged) flood occurred on April 12, 1922, when the water surface reached elevation 289.9. For this water level, the computed discharge is 56,876 cfs.

The flood of March 28, 1913 closely correlates with the Corps of Engineers HEC computer simulation of the 100-year event (90,000 cfs) for the Hudson River basin above the confluence of the Hudson and Sacandaga Rivers near Lake Luzerne (drainage area - 2708 square miles). Hence, if this flood of record were to occur again, the computed water surface elevation would be 292.45 and the present dam would be overtopped to a depth of 2.45 feet.

#### 5.6 OVERTOPPING POTENTIAL

Analysis indicates the spillway does not have sufficient discharge capacity for either the PMF or one-half the PMF. The computed depths of overtopping are 13.3 feet and 6.2 feet respectively. All storms exceeding approximately 19% of the PMF would result in overtopping of the North Bulkhead and the South Abutment wall.

#### 5.7 EVALUATION

The spillway capacity is inadequate for the peak outflow from one-half the PMF. For such a large storm event, a high tailwater condition would most likely occur resulting in the flooding of the downstream hazard areas. Hence, the spillway capacity is not considered to be seriously inadequate since dam failure from overtopping would not significantly increase the hazard to loss of life downstream from that which would exist just before overtopping failure.

Another reason why the spillway is not assessed as seriously inadequate is that the Corps of Engineers report does not properly consider the flood storage capability of Conklingville Dam at the Sacandaga Reservoir. This structure's primary purpose is flood control. The Hudson - Black River Regulating District operates this structure so that the water surface is at least 3 feet below the spillway crest. This three foot depth will provide about 75,000 acre-feet of storage. Prior to the Spring runoff period, the normal water surface is kept about 10 feet below the spillway crest. Further evidence in support of the flood control capability of this dam is that there has been no flow over the crest of the spillway since the structure was completed in 1930.

## SECTION 6: STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

#### a. Visual Observations

Visual observations of the spillway crest did not reveal any signs of major distress. Although the concrete surface was deteriorated, this condition was not so serious as to affect the stability of the dam.

The poor condition of the North Bulkhead could affect the integrity of this structure. Concrete deterioration of the buttress walls and structural cracking at the Bay 6 - spillway abutment contact are evidence of the weakened condition of this section of the dam. Visual observations of the remaining appurtenant structures did not reveal any other signs of major distress.

#### b. Design and Construction Data

No design computations or other data concerning the structural stability of the entire dam were available.

#### c. Data Review and Stability Evaluation

The NYS-DOT plans show a cross section of the spillway. A stability analysis was performed using the cross-section information shown, plus simplifying assumptions made in the analysis.

Analyses were performed assuming that the concrete key extending 4 feet into bedrock under the upstream toe was intact. A separate analysis was also performed assuming the concrete key separated from the dam and no longer functioned as part of the structure. Conditions analyzed were:

- 1) Normal conditions with the water level at the spillway crest elevation.
- 2) Conditions as in 1), plus a 10,000 lb/ft ice load.
- 3) Water level at the elevation of one-half PMF; a flow depth of 15 feet.
- 4) Conditions as in 3), but with the concrete key separated from the dam.

The safety factors for overturning and sliding for the spillway section only, obtained from the analyses are:

CONDITION	FACTOR OF SAFETY	
	OVERTURNING	SLIDING
1) Normal water level	21.40	38.22
2) Ice load plus 1)	17.86	27.18
3) One-half PMF	14.95	35.75
4) One-half PMF; no key	1.45	18.06

The analyses indicate that the factors of safety for all conditions analyzed are acceptable. Only for condition 4 (one-half the PMF and the key under the upstream toe offering no passive resistance) does the factor of safety fall below the recommended guidelines.

The spillway was considered to be the critical portion of the dam for the stability analysis, since failure of this section would result in a substantial flood wave. While the North Bulkhead (section C-C on the as-built plans) appears to be a more critical section for stability considerations, failure of this portion of the dam would simply open the 6 lift gates without affecting the stability of the main dam.

d. Post Construction Changes

The changes to the entire river structure do not appear to have significantly altered the structural stability of the dam. The conversion of the former bypass and navigation lock into the present Feeder Canal Intake Structure occurred primarily within the limits of the bypass-lock structure. The construction of the hydroelectric power station adjoining the South Bulkhead buttresses the dam at the Spillway - South Bulkhead contact.

e. Seismic Stability

The dam is located in Seismic Zone 2. While the dam appears to be relatively stable, a seismic stability analysis was performed in accordance with the Corps of Engineer's guidelines. The seismic analysis was performed for normal conditions with the water level at the spillway crest. The safety factor against overturning with seismic considerations included is 20.58 and against sliding is 37.97.

## SECTION 7: ASSESSMENT/RECOMMENDATIONS

### 7.1 ASSESSMENT

#### a. Safety

The Phase 1 inspection of the Feeder Dam did not reveal conditions which constitute an immediate hazard to human life or property. The North Bulkhead, however, does exhibit significant deficiencies and deterioration that could affect its future structural integrity. The spillway and appurtenant structures, are not presently considered to be unstable.

The spillway capacity, although not having sufficient discharge capacity for passing one-half the PMF, is considered to be inadequate. During periods of unusually heavy precipitation, continuous surveillance should be provided both at the dam (especially at the North Bulkhead) and in the downstream areas to warn of hazardous flooding conditions. Such surveillance procedures and other measures should be documented in a detailed emergency-operation plan for the dam. Also, a warning system should be developed and placed in readiness for future use.

#### b. Adequacy of Information

The information available appears to be adequate for the purposes of the Phase 1 inspection.

#### c. Urgency

The deficiencies occurring at the North Bulkhead require priority remedial action in order to prevent further deterioration of this part of the dam. Such remedial action and corrective measures should be completed prior to the next period of anticipated high river flows (Spring 1980). Since the deficiencies at the 615 foot long spillway-overflow section encompass the entire concrete surface, secondary emphasis should be placed on rehabilitating this portion of the dam also. Such remedial measures should be completed following the restoration of the North Bulkhead. All other deficiencies observed during the visual inspection can be corrected during normal maintenance operations.

#### d. Necessity for Additional Investigations

Further structural analysis of the North Bulkhead to ascertain the integrity of this part of the entire dam is recommended. In addition, information regarding the location and top elevations of the former removed dam with respect to the existing structure is desirable since no such information presently exists.

### 7.2 RECOMMENDED MEASURES

The following actions should be undertaken:

#### A) North Bulkhead:

- 1) Eliminate the leakage through all concrete members.
- 2) Rehabilitate the deteriorated concrete buttress walls.
- 3) Repair the structural cracking and vertical displacement of the Bay 6 top slab - spillway abutment contact.

- 4) Rehabilitate the lift-gate machinery so as to make them operable.
- 5) Rehabilitate all deteriorated and cracked concrete surfaces.
- 6) Eliminate the leakage through the gates themselves.

B) Other:

- 7) Perform periodic operation and maintenance on the tainter gate, needle dam, and the canal sluice gate hoist machinery.
- 8) Establish and maintain an operating mechanism for the South Bulkhead gates.
- 9) Rehabilitate all deteriorated and cracked concrete surfaces.
- 10) Develop and implement a detailed emergency-operation plan and warning system.
- 11) As a result of the completed additional investigations, further remedial measures deemed necessary should be completed within two years of the date of this report.


APPENDIX A

PHOTOGRAPHS






FEEDER DAM SPILLWAY WITH FLASHBOARDS  
(Looking South)



CONCRETE SURFACE DETERIORATION AND EROSION




NORTH BULKHEAD (Looking South)




NORTH BULKHEAD  
(Note-flow occurring from leakage through the structure)




BUTTRESS WALL 1/2 - LEAKAGE THRU CONCRETE  
(North Side)



BUTTRESS WALL 1/2 - LOSS OF THICKNESS  
(North Side)




BAY 6 - SPILLWAY ABUTMENT CONTACT  
(Note - Structural cracking)




FEEDER CANAL INTAKE STRUCTURE - TAINIER GATE



FEEDER CANAL DISCHARGE CONTROL STRUCTURES



SOUTH BULKHEAD WITH GATES  
(Looking North)



HYDROELECTRIC POWER STATION TAILRACE  
AND ICE SLUICE

APPENDIX B

ENGINEERING DATA CHECKLIST

Check List  
Engineering Data  
Design Construction Operation

Name of Dam FEEDER DAM @  
GLENS FALLS  
I.D. # NY-143  
(378-UH)

Item	Remarks		
	Plans	Details	Typical Sections
Dam	YES	YES	YES
Spillway(s)	YES	YES	YES
Outlet(s)	YES	YES	YES
Design Reports	NO		
Design Computations	NO		
Discharge Rating Curves	NO		
Dam Stability	NO		
Seepage Studies	NO		
Subsurface and Materials Investigations	NO		



# FEEDER DAM @ GLENS FALLS

Item Remarks

Construction History LIMITED TO ( 1916 & 1933 DAM INSPECTION REPORTS)

MODIFICATIONS:  
FEEDER CANAL INTAKE STRUCTURE  
HYDROELECTRIC POWER STATION

NONE

MEAN DAILY WATER LEVEL & RECORDS @ ENTRANCE TO  
FEEDER CANAL (10/1916 TO 6/1961)

Item

Construction History

Surveys, Modifications,  
Post-Construction Engineering  
Studies and Reports

Accidents or Failure of Dam  
Description, Reports

Operation and Maintenance Records  
Operation Manual

APPENDIX C

VISUAL INSPECTION CHECKLIST

# VISUAL INSPECTION CHECKLIST

## 1) Basic Data

### a. General

Name of Dam FEEDER DAM @ GLENS FALLS

I.D. # NY-143

Location: Town QUEENSBURY MOREAU County WARREN - SARATOGA

Stream Name HUDSON RIVER

Tributary of N/A

Latitude (N) 43°-17'-30" Longitude (W) 73°-40'-00"

Hazard Category C

Date(s) of Inspection 11/2/78

Weather Conditions ± 45° CLEAR

b. Inspection Personnel R. WARRENDER W. LYNICK

c. Persons Contacted J. HUNTINGTON (NYS DOT REGION ONE - WATERWAYS)  
W. COLLIGAN  
NYS DOT - WATERWAYS SUBDIV. (MAIN OFFICE)

### d. History:

Date Constructed 1913

Owner NYS-DOT WATERWAYS MAINT. SUBDIVISION

Designer NYS DEPT. OF PUBLIC WORKS (NOW NYS DOT)

Constructed by NYS DEPT. OF PUBLIC WORKS

## 2) Technical Data

Type of Dam CONCRETE GRAVITY DAM w/ APPURTENANT STRUCTURES

Drainage Area 2801 SQ. MILES

Height 36' Length 615'(+)

Upstream Slope N/A Downstream Slope N/A

2) Technical Data (Cont'd.)External Drains: on Downstream Face N/A @ Downstream Toe N/A

## Internal Components:

Impervious Core N/ADrains NONECutoff Type N/AGrout Curtain NONE

4) Instrumentation

(1) Monumentation/Surveys WATER SURFACE STAFF GAGE ABOVE  
THE DAM - ATTACHED @ FEEDER CANAL INTAKE STRUCTURE

(2) Observation Wells NONE

(3) Weirs NONE

(4) Piezometers NONE

(5) Other \_\_\_\_\_

5) Reservoir

a. Slopes N/A HUDSON RIVER SHORELINE ; TREES & BRUSH  
TO RIVER'S EDGE

b. Sedimentation N/A

6) Spillway(s) (including Discharge Conveyance Channel)

WITH FLASHBOARDS (2.9' HIGH) CONCRETE GRAVITY STRUCT.

a. General \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

b. Principle Spillway HORIZ & VERTICAL ALIGNMENT - SATISFACTORY  
FLASHBOARDS - BOXED IN 3 LOCATIONS ; RELATIVELY NEW &  
IN SATISFACTORY CONDITION  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

c. Emergency or Auxiliary Spillway NONE  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

d. Condition of Discharge Conveyance Channel - HUDSON RIVER ; SATISFACTORY  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

e. Stability of Channel side/slopes N/A  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

7) Downstream ChannelHUDSON RIVERa. Condition (debris, etc.) SATISFACTORY TREES & BRUSHGROW TO RIVER'S EDGEb. Slopes N/Ac. Approximate number of homes CITIES OF SOUTH GLENS FALLS& GLENS FALLS8) Reservoir Drain/OutletType: Pipe \_\_\_\_\_ Conduit \_\_\_\_\_ Other NONE

Material: Concrete \_\_\_\_\_ Metal \_\_\_\_\_ Other \_\_\_\_\_

Size: \_\_\_\_\_ Length \_\_\_\_\_

Invert Elevations: Entrance \_\_\_\_\_ Exit \_\_\_\_\_

Physical Condition (describe): \_\_\_\_\_ Unobservable \_\_\_\_\_

Material: \_\_\_\_\_

Joints: \_\_\_\_\_ Alignment: \_\_\_\_\_

Structural Integrity: \_\_\_\_\_

Hydraulic Capability: \_\_\_\_\_

Means of Control: Gate \_\_\_\_\_ Valve \_\_\_\_\_ Uncontrolled \_\_\_\_\_

Operation: Operable \_\_\_\_\_ Inoperable \_\_\_\_\_ Other \_\_\_\_\_

Present Condition (describe): \_\_\_\_\_

9) Structural

- a. Concrete Surfaces SPILLWAY CREST - UNEVEN DETERIORATED SURFACE - NO SMOOTH CONC. AREA REMAINING ; 2 LARGE EROSION DEPRESSIONS NORTH OF LOGWAY  
AGGREGATE HOLES - VISIBLE
- SURFACE DETERIORATION - TOP SLAB @ BAY 1  
NORTH BULKHEAD BASE SLAB - DETERIORATION SIMILAR TO SPILLWAY CREST  
LESSER AREAS OF SPALLING ON ALL CONCRETE SURFACES
- b. Structural Cracking NORTH BULKHEAD TOP SLAB - @ MIDPTS & @ ENDS OF EACH BAY ; ALSO BETWEEN ANCHOR BOLTS FOR GATE MACHINERY  
OTHER SURFACE CRACKING ON CONCRETE SURFACES  
SIGNIFICANT @ BAY 6 - SPILLWAY ABUTMENT CONTACT (ALSO SETTLEMENT)
- c. Movement - Horizontal & Vertical Alignment (Settlement) BAY 6 - SPILLWAY ABUTMENT CONTACT - VERTICAL DISPLACEMENT
- d. Junctions with ~~Abutments or~~ Embankments SOME SOIL EROSION @ SOUTH ABUTMENT WALL @ RIVER'S EDGE (NO EFFECT ON WALL)  
SPILLWAY JUNCTION W/ NORTH BULKHEAD - SATISFACTORY  
W/ SOUTH BULKHEAD - UNKNOWN
- e. Drains - Foundation, Joint, Face N/A
- f. Water passages, conduits, sluices NORTH BULKHEAD - SIGNIFICANT LEAKAGE THRU CONCRETE BUTTRESS WALLS BETWEEN GATES ; GATE MACHINERY - INOPERATIVE AND/OR NON-EXISTENT  
FEEDER CANAL INTAKE STRUCTURE - TAINTER GATE, NEEDLE DAM ; SLUICE GATES SATISFACTORY  
SOUTH BULKHEAD (INTO FOREBAY) - SATISFACTORY ; NO GATE MACHINERY
- g. Seepage or Leakage FLASHBOARDS - MINOR  
NORTH BULKHEAD - SIGNIFICANT ; THRU CONCRETE ; THRU WOOD GATES  
FEEDER CANAL (CHANNEL) - ALONG MASOURY RIVER-SIDE WALL , @ SLUICE-GATE WELL DOWNSTREAM OF DAM



- h. Joints - Construction, etc. N/A
- i. Foundation NORTH BULKHEAD BASE SLAB - CONCRETE DETERIORATION  
SIMILAR TO SPILLWAY CREST SURFACE (AGGREGATE HOLES)
- j. Abutments NORTH & SOUTH ABUTMENT WALLS - SATISFACTORY
- k. Control Gates NORTH BULKHEAD - INOPERATIVE AND/OR NON-EXISTENT  
SOUTH BULKHEAD - NON-EXISTENT  
FEEDER CANAL INTAKE STRUCTURE - FUNCTIONING SATISFACTORILY
- l. Approach & Outlet Channels N/A
- m. Energy Dissipators (plunge pool, etc.) NONE
- n. Intake Structures N/A
- o. Stability N/A
- p. Miscellaneous

APPENDIX D

HYDROLOGIC/HYDRAULIC

ENGINEERING DATA AND COMPUTATIONS

FEEDER DAM @  
GLENS FALLS

1

CHECK LIST FOR DAMS  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

AREA-CAPACITY DATA:

BARGE CANAL DATUM - BCD

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam (NORTH BULKHEAD)	<u>290.0</u>	<u>493</u>	<u>10100</u>
2) Design High Water (Max. Design Pool)	<u>N/A</u>	<u>          </u>	<u>          </u>
3) Auxiliary Spillway Crest	<u>N/A</u>	<u>          </u>	<u>          </u>
4) Pool Level with Flashboards	<u>284.9</u>	<u>493</u>	<u>7600</u>
5) Service Spillway Crest	<u>282.0</u>	<u>493</u>	<u>6200</u>

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily	<u>N/A</u>
2) Spillway @ Maximum High Water (WITHOUT FLASHBOARDS)	<u>58000</u>
3) Spillway @ Design High Water	<u>N/A</u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>N/A</u>
5) Low Level Outlet	<u>N/A</u>
6) Total (of all facilities) @ Maximum High Water	<u>          </u>
7) Maximum Known Flood (RECORDED)	<u>56800</u>
8) HYDROELECTRIC POWER STATION MACHINERY (5 UNITS)	5000 (MAX)

CREST:

ELEVATION: 290.0 (BCD)Type: CONCRETE GRAVITY (INCL - SPILLWAY NORTH BULKHEAD FEEDER CANAL INTAKE)  
STRUCTURE, NORTH ABUTMENT WALL, SOUTH BULKHEAD, SOUTH ABUTMENT WALLWidth: VARIABLE Length: 1044'Spillover CREST OF SPILLWAYLocation CENTER

SPILLWAY:

PRINCIPAL

EMERGENCY

282.0 (BCD) Elevation                     OGEE ; CONCRETE GRAVITY Type NONE  
w/ FLASHBOARDS                                     Width                     Type of Control✓ Uncontrolled                     

Controlled:

2-9' FLASHBOARDS Type                       
(NOT @ LOGWAY) (Flashboards; gate)CONTINUOUS ACROSS CREST Number                     615' Size/Length                     Invert Material                     Anticipated Length  
of operating service                     N/A Chute Length                     >6' Height Between Spillway Crest  
& Approach Channel Invert  
(Weir Flow)

OUTLET STRUCTURES/~~EMERGENCY DRAWDOWN FACILITIES:~~Type: Gate ✓ Sluice ✓ Conduit \_\_\_\_\_ Penstock \_\_\_\_\_Shape : NORTH BULKHEAD - FEEDER CANAL INTAKE STRUCTURE ;  
SOUTH BULKHEAD

Size: \_\_\_\_\_ SEE DRAWINGS

Elevations: Entrance Invert \_\_\_\_\_

Exit Invert \_\_\_\_\_

Tailrace Channel: Elevation - RIVER BOTTOM

## HYDROMETEROLOGICAL GAGES:

Type : STAFF GAGE STAFF GAGE @ FEEDER CANAL  
INTAKE STRUCTURELocation: SPIER FALLS DAM

Records: (USGS)

Date - 10/1912 TO 3/1923 10/1916 TO 6/1961Max. Reading - 89,100 cfs 3/28/1913 289.9 4/12/1922

## FLOOD WATER CONTROL SYSTEM:

Warning System: NONE

Method of Controlled Releases (mechanisms):

NONE

DRAINAGE AREA: 2801 SQ MILES

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: 3/4(+) OF AREA IN ADIRONDACK MOUNTAIN AREA

Terrain - Relief: ELEVATIONS ( +5344 TO +290 @ DAM )

Surface - Soil: VARIES

Runoff Potential (existing or planned extensive alterations to existing  
(surface or subsurface conditions)

N/A SACANDAGA LAKE (CONKLINGVILLE DAM)  
FLOOD STORAGE - ATTENUATION

Potential Sedimentation problem areas (natural or man-made; present or future)

N/A

Potential Backwater problem areas for levels at maximum storage capacity  
including surcharge storage:

N/A

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the  
Reservoir perimeter:

Location: N/A

Elevation: \_\_\_\_\_

Reservoir:

Length @ Maximum Pool 6.8± (Miles)

Length of Shoreline (@ Spillway Crest) N/A (Miles)

## PROJECT GRID

JOB	FEEDER DAM @ GLENS FALLS		SHEET NO.	1/	CHECKED BY	DATE
SUBJECT	DRAINAGE AREA ADJUSTMENT - H.E.H.		COMPUTED BY	WCL	DATE	4/9/79
DRAINAGE AREA:						
WSP # 1302		GAGE # 46 @ SPIER FALLS DAM		DA = 2779 SQ MILES		
GAGE # 47 IS IN THE FEEDER CANAL						
M.X. Q:		89,100 cfs ON 3/23/1913		OR (32.06 csm)		
USGS 7.5' QUAD SHTS: CONTRIBUTING AREA TO FEEDER DAM						
BELOW SPIER FALLS DAM						
SCALE: 1:24000						
1" = 2000'						
1 SQ IN = 914.827 ACRES						
QUAD SHT	(PLANIMETERED) AREA					
CORINTH	5.73"					
GANSEVOORT	10.39"					
LAKE LUZERNE	8.09"					
	0.03"					
	10.40"					
	18.52"					
GLENS FALLS	39.00"					
	34.41"					
	5.43"					
	31.80"					
	11.65"					
	122.34"					
TOTAL:	156.95 SQ IN → 14415 ACRES → 22.52 SQ MILES					
	[USE 22 SQ MI.] ←					
∴ DRAINAGE AREA (FEEDER DAM)	= 2801 SQ MILES ←					

## PROJECT GRID

JOB FEEDER DAM @ GLENS FALLS	SHEET NO. 2/	CHECKED BY	DATE
SUBJECT DISCHARGE COEFFICIENT - SPILLWAY CREST		COMPUTED BY JC	DATE 4/10/70

REF: USBR REC - DESIGN OF SMALL DAMS (1977)  
FIG. 249 & 250

ANALYSIS CONDITIONS:

1)  $P = 18$     $H_o = 8$     $\frac{P}{H_o} = 2.25$     $C_o = 3.94$   
 $P = 6$     $H_o = 8$     $\frac{P}{H_o} = 0.75$     $C_o = 3.86$

NIAGARA-MOHAWK POWER CORP:  
 FLASHBOARDS ARE DESIGNED FOR FAILURE WITH A HEAD OF 18" - 24" (USE 24")  
 $\therefore$  DESIGN HEAD (FLASHBOARDS) = 286.9 (USE 287.0)

2)  $P = 18$     $H_o = 5$     $\frac{P}{H_o} = 3.60$     $C_o = 3.95 +$  (OFF FIG. 249)  
 $P = 6$     $H_o = 5$     $\frac{P}{H_o} = 1.20$     $C_o = 3.90$

DESIGN HIGHWATER = 287.0  
 DESIGN HEAD;  $H_o = 5$   
 FOR  $P = 6$   
 (DESIGN) DISCHARGE COEFF.  $C_o = 3.90$   
 $Q_o = 26,816$  cfs



## PROJECT GRID

JOB FEEDER DAM @ GLENS FALLS		SHEET NO. 3/		CHECKED BY		DATE	
SUBJECT DISCHARGE COEFFICIENT (VARIATION WITH HEAD) - SPILLWAY CREST (ONLY)		COMPUTED BY JCL		DATE 4/10/79			
USBURSC (1977) - FIG. 250							
$H_0 = 5$		$C_0 = 3.90$		(NO FLASHBOARDS)		$Q = CL H^{3/2}$ $L = 415'$	
STAGE	DEPTH FLOW ( $H_0$ )	$H_0/H_1$	$C/C_0$	DISCHARGE COEFF. ( $C$ )	$Q$ (cfs)		
292.0	10	— (OFF FIG. 250) —		4.2	81682		
TOP OF NORTH BULKHEAD	290.0	8	1.6	1.07	4.17	58029	
	289.9	7.9	1.58	1.068	4.165	56876	
	289.0	7	1.4	1.048	4.09	46585	
	288.0	6	1.2	1.026	4.00	36154	
	286.0	4	0.8	0.97	3.78	18598	
	284.9	2.9	0.58	0.934	3.64	11055	
	283.0	1	0.2	0.852	3.32	2041.8	
	282.0	0	—	0.8	3.12	0	
				[ FIG. 249: MINIMUM $C_0$ FOR THIS SHAPE CREST IS 3.1			
CONTINUED:							
STAGE						$Q$ (cfs)	
297.0	15				4.2	150059	
296.0	14				↑	135306	
295.0	13					121071	
294.0	12					107373	
293.0	11				↓	94635	

## PROJECT GRID

JOB	FEEDER DAM @ GLENS FALLS		SHEET NO.	4/	CHECKED BY	DATE
SUBJECT	SIMULATION DATA - STANDARD PROJECT FLOOD (SPF)		COMPUTED BY	WCL	DATE	11/10/79
"UPPER HUDSON & MOHAWK RIVER BASINS HYDROLOGIC FLOOD ROUTING MODELS"						
1) DRAINAGE BASIN -- UPPER HUDSON TO A POINT JUST BELOW THE CONFLUENCE OF SARANDAGA & HUDSON RIVERS						
TOTAL AREA = 2722 SQ MILES						
CONTROL POINT		HYDROGRAPH VALUE (CFS)				
1044		(PEAK) 128420		103772		
1047		42314		44739 (PEAK)		
(TOTAL)		170734		148511		
1048 = (1044 + 1047)		154540 cfs (PEAK)		(SPF)		
		(56.77 csm)				
2) DRAINAGE BASIN - BELOW 1048 TO GLENS FALLS (POSSIBLY NOT FEEDER DAM)						
SUBBASIN AREA = 84 SQ MILES		23834 (PEAK)		HYDROGRAPH VALUE		
#257						
CONTROL POINT		PEAK FLOW				
1257		149725 cfs		(SPF)		
AREA = 2800		SQ MILES (53.36 csm)				
3) FIG. 6.52: DRAINAGE AREA VS PEAK DISCHARGE (SPF-CURVE)						
FOR AREA = 2800 SQ MILES		PEAK = 55 csm				

## PROJECT GRID

JOB	FEEDER DAM @ GLEUS FALLS	SHEET NO.	5/	CHECKED BY		DATE	
SUBJECT	SIMULATION DATA - PMF DETERMINATION			COMPUTED BY	DCL		DATE
SPS RAINFALL - 9.5" (SIMULATION)							
SPF RAINFALL (SUBBASIN #257) - 12.5"							
TRANPOSED AGUES RAINFALL - 13.1" ← OVER ENTIRE BASIN MAX - 17" AND 15"; MIN - 10"							
DEC. 1948 STORM RAINFALL - 8" MAX							
JUN. 1972 STORM - 5" MAX							
PMP RAINFALL - (NWS TP-40) - 20"-21" (10 SQ MILE - 6 HR)							
PMP RAINFALL - (HRR #23) - 18.2" (200 SQ MILE - 24 HR)							
75% (1000 SQ MI - 24 HR) - 14.2"							
25% (1000 SQ MI - 48 HR) - 15.6"							
PMF $\approx$ 2 X SPF							
FOR PMF OUTFLOW:							
FOR 2801 SQ MILES @ 53.3% CSM X 2 = 298,923 cfs							
USE 299,000 cfs ←							
$\frac{1}{2}$ PMF = 149,500 cfs ←							

## PROJECT GRID

JOB FEEDER DAM @ GLENS FALLS		SHEET NO. 6/	CHECKED BY	DATE
SUBJECT DISCHARGE COEFFICIENTS - APPURTENANT STRUCTURES		COMPUTED BY OCL		DATE 1/16, 79
NORTH BULKHEAD:		RE: HAUBROOK ICE HYDRAULICS KING & BRATER 15TH EDITION		
TOP - 290.0		(pg. 5-24)		
LENGTH - 114'				
WIDTH - 8' @ GATE				
10' @ BUTRESS WALL		ALL - BROAD CRESTED WEIRS		
		USE C = 3.087 FOR OVERTOPPING		
FEEDER CANAL INTAKE STRUCTURE:				
TOP - 292.0				
LENGTH - 64'				
WIDTH - > 10'				
NORTH ABUTMENT WALL:				
TOP - 292.0				
LENGTH - 65'				
WIDTH - > 5'				
SOUTH BULKHEAD:				
TOP - 297.0				
LENGTH - 151'				
WIDTH - 8' @ GATE				
10' @ BUTRESS WALL				
SOUTH ABUTMENT WALL:				
TOP - 290.0				
LENGTH - 35'				
WIDTH - 3' (+ EXISTING GROUND)				

## PROJECT GRID

JOB			SHEET NO.		CHECKED BY		DATE	
FEEDER DAM @ GLENS FALLS			7/					
SUBJECT					COMPUTED BY		DATE	
DISCHARGES - APPORTENANT STRUCTURES					JCL		4/2/79	
$Q = CUH^{3/2}$ (SEE SHT 6-L) (SPILLWAY DISCHARGES)								
C = 3.087 ALL STRUCTURES (FOR OVERTOPPING) SHT 3								
		FEEDER CANAL INTAKE STRUCTURE		NORTH ABUTMENT WALL		SOUTH ABUTMENT WALL (INTO FOREBAY)		TOTAL DISCHARGE
STAGE	NORTH BULKHEAD							
TOPT	290.0		292.0		292.0		297.0	290.0
290.0	0		0		0		0	0
291.0	(1) 352		0		0		(1) 108	460
292.0	(2) 995		0		0		(2) 306	1301
293.0	(3) 1829	(1) 198	(1) 201		0		(3) 561	2789
294.0	(4) 2815	(2) 559	(2) 568		0		(4) 864	4806
295.0	(5) 3935	(3) 1027	(3) 1043		0		(5) 1208	7213
296.0	(6) 5172	(4) 1581	(4) 1605		0		(6) 1528	9946
297.0	(7) 6518	(5) 2209	(5) 2243		0		(7) 2001	12971

## PROJECT GRID

JOB FEEDER DAM @ GLENS FALLS				SHEET NO. 8/		CHECKED BY		DATE	
SUBJECT DISCHARGES THRU BULKHEAD GATES						COMPUTED BY JNL		DATE 2/20/70	

SOUTH BULKHEAD				NORTH BULKHEAD			
#GATES = 8				#GATES = 6			
AREA (EACH) = 202.51 ft <sup>2</sup>				AREA (EACH) = 111.9 ft <sup>2</sup>			
SIZE: 13.5' H x 15' W				SIZE: 7.5' H x 14.92' W			
TOP ELEV. = 283.5				TOP ELEV. = 283.5			
BOTTOM " = 270.0				BOTTOM " = 276.0			

FLOW EQUATIONS:

WEIR FLOW  $Q = CLH^{3/2}$  WHERE  $L = L' - 2(NK_p + K_o)H_e$   $C = 2.63$

ROUND-NOSED PIERS  $K_p = 0.01$

ABUTMENT EFFECT  $K_o = 0$  (ROUNDED ABUTMENTS)

ORIFICE FLOW  $Q = CA\sqrt{2gH}$  WHERE  $C = 0.6$

(SUBMERGENCE)  $H$  - MEASURED TO ELEV. OF ORIFICE

SOUTH BULKHEAD				NORTH BULKHEAD			
$L' = 120'$ $N = 7$				$L' = 89.5'$ $N = 5$			
$\therefore L = 120 - 2[(7)(0.01) + 0]H_e$				$\therefore L = 89.5 - 2[(5)(0.01) + 0]H_e$			
$\rightarrow L = 120 - 0.14H_e$				$\rightarrow L = 89.5 - (0.1)H_e$			
$C = 2.63$				$C = 2.63$			


  

STAGE	$H_e$	L	Q (cfs)	STAGE	$H_e$	L	Q (cfs)	TOTAL DISCHARGE
270.0	0	—	0					0
272.0	2	119.72	891					891
274.0	4	119.44	2513					2513
276.0	6	119.16	4606	276.0	0	—	0	4606
278.0	8	118.88	7075	278.0	2	89.3	664	7739
280.0	10	118.60	9864	280.0	4	89.1	1875	11739
282.0	12	118.32	12936	282.0	6	88.9	3436	16372
283.5	13.5	118.11	15408	283.5	7.5	88.75	4794	20202

WEIR FLOW ↑  
ORIFICE FLOW ↓

HANDBOOK  
OF  
HYDRAULIC  
5TH ED.  
TABLE 5-3

## PROJECT GRID

JOB FEEDER DAM @ GLENS FALLS				SHEET NO. 9/		CHECKED BY		DATE		
SUBJECT DISCHARGES THRU BULKHEAD GATES						COMPUTED BY JCL		DATE 1/16/79		
$Q = C A \sqrt{2gH}$ (EMERGENCE)										
$C = 0.6$										
SOUTH BULKHEAD					NORTH BULKHEAD					
$A = 202.5 \text{ ft}^2$ (EACH)					$A = 111.9 \text{ ft}^2$ (EACH)					
# GATES = 6					# GATES = 6					
$\bar{C}$ ELEV. = 276.75					$\bar{C}$ ELEV. = 279.75					
										
STAGE	H	Q	6Q	ORIFICE FLOW ↓	STAGE	H	Q	6Q	TOTAL DISCHARGE:	
283.5	6.75	2533	20264		283.5	3.75	1043	6258		26522
284.0	7.25	2625	21000		284.0	4.25	1111	6666		27666
284.9	8.15	2784	22272		284.9	5.15	1223	7338		29610
286.0	9.25	2965	23720		286.0	6.25	1347	8082		31802
288.0	11.25	3270	26160		288.0	8.25	1548	9288		35448
289.0	12.25	3413	27304		289.0	9.25	1639	9834		37138
290.0	13.25	3549	28392		→ 290.0	10.25	1725	10350		38742
291.0	14.25	3681	29448		291.0	11.25	1807	10842		40290
292.0	15.25	3808	30464		292.0	12.25	1886	11316		41780
293.0	16.25	3930	31440		293.0	13.25	1961	11766		43206
294.0	17.25	4050	32400		294.0	14.25	2034	12204		44604
295.0	18.25	4165	33320		295.0	15.25	2104	12624		45944
296.0	19.25	4275	34224		296.0	16.25	2172	13032		47256
297.0	20.25	4388	35104		← 297.0	17.25	2238	13428		48532

## PROJECT GRID

JOB FEEDER DAM @ GLENS FALLS		SHEET NO. 10/		CHECKED BY	DATE
SUBJECT DISCHARGES THRU SLICE GATES (FEEDER CANAL INTAKE STRUCTURE)		COMPUTED BY WCL		DATE 4/10/79	

SLICE GATES					
# GATES = 2					
AREA (EACH) = 48 ft <sup>2</sup>					
SIZE: 8'H x 6'W					
TOP ELEV. = 287.5					
BOTTOM ELEV. = 279.5					
FLOW EQUATIONS:					
WEIR FLOW		$Q = C L H^{3/2}$ WHERE $L = L' - 2K_2 H$		C = 2.63	
		$L = L' - 0.4H$			
		ABUTMENT EFFECT $K_2 = 0.2$			
ORIFICE FLOW (SUBMERGENCE)		$Q = C A \sqrt{2gH}$		WHERE C = 0.6	
		H - MEASURED TO C ELEV. OF ORIFICE			

STAGE	H	L	Q (cfs)	2Q
279.5	0	—	0	0
280.0	0.5	5.8	5.4	10.8
282.0	2.5	5.0	52	104
283.5	4.0	4.4	93	186
284.0	4.5	4.2	105	210
284.9	5.4	3.84	127	254
286.0	6.5	3.4	148	296
287.5	8.0	2.8	167	334
ORIFICE H:				
288.0	8.5	4.5	490	980
289.0	9.5	5.5	542	1084
290.0	10.5	6.5	589	1178
292.0	12.5	8.5	674	1348





## PROJECT GRID

JOB	FEEDER DAM @ GLEN'S FALLS		SHEET NO.	12/	CHECKED BY	DATE
SUBJECT	RESERVOIR - STORAGE CAPACITY		COMPUTED BY	JCL	DATE	4/16/79

USGS 7.5' QUAD SHT:

CONTOUR 290 (NEAR SHERMAN ISLAND POWERPLANT)

ELEVATION 282 (SPILLWAY CREST)

Distance = 32100'

$\Delta h = 8'$

$\frac{8'}{32100} = 0.000249$

AVERAGE WIDTH  $\approx 600'$

$= 0.25' / 1000'$  (SLOPE)

ELEVATIONS (RIVER BOTTOM):

USE 265.0

NORTH BULKHEAD - 264.0

SOUTH BULKHEAD - 265.0

WATER SURFACE PROFILE @ 0.25'/1000'

290.0

284.9

282.0

265.0

264.0

276.0

265.0

32100'

35800'

3700'

CONTOUR 290

SHERMAN ISLAND DIVERSION DAM

RIVER BOTTOM SLOPE

FLASHBOARDS

SPILLWAY

LOGWAY CREST

NORTH BULKHEAD


SOUTH BULKHEAD

STORAGE CAPACITY:

LOGWAY CREST -	SPILLWAY CREST -	FLASHBOARDS -
$V = \frac{(6.1 + 15)}{2} \times \frac{35800 \times (600)}{43560}$	$V = \frac{(8.1 + 17)}{2} \times \frac{35800 \times (600)}{43560}$	$V = \frac{(11 + 19.9)}{2} \times \frac{35800 \times (600)}{43560}$
$V = 5202 \text{ ACRE-FT}$	$V = 6189 \text{ ACRE-FT}$	$V = 7619 \text{ ACRE-FT}$

NORTH BULKHEAD -

$V = \frac{(16.1 + 25)}{2} \times \frac{35800 \times (600)}{43560} = 10133 \text{ ACRE-FT}$



DRAINAGE AREA -  
FEEDER DAM @  
GLENS FALLS

WSP #1303  
SCALE  
1:1,000,000

River at Conklingville, N. Y.

June	July	Aug.	Sept.	The year
0.96	0.42	0.25	0.15	39.04
1.76	.41	.38	.23	32.40
5.85	.39	.51	.65	27.50
1.66	*.35	.25	*.72	18.02
1.05	.23	.21	.60	29.95
1.29	.25	.15	.19	30.14
.54	.43	.35	.51	23.71
.53	3.08	3.18	.97	22.63
1.09	*1.03	*.27	*.35	27.01
1.43	*1.31	*.45	*.31	27.20
.12	*.73	*.23	*.82	25.33
.24	.11	.75	.96	28.85
.21	.15	.55	.40	20.55
.49	1.77	*.48	*.26	26.86
.71	2.06	.94	.50	33.47
.81	.40	.20	.43	23.93
.94	.47	.34	.77	30.23
1.33	2.44	1.72	1.05	30.12
1.02	1.00	.65	1.27	32.19
1.12	.75	1.08	1.40	27.74
1.19	2.08	1.03	.71	36.80
.58	1.22	.44	1.04	31.03

Published.

Calendar year		Observed		Adjusted	
Per square mile	Runoff in inches	Mean	Mean	Runoff in inches	Mean
1.15	15.74	-	2,360	30.48	-
1.33	15.43	-	2,480	31.99	-
1.23	27.50	-	2,240	28.80	-
1.33	18.05	-	1,970	25.28	-
2.20	29.95	-	2,120	27.28	-
2.22	30.14	-	2,200	28.26	-
1.74	23.71	-	1,600	20.52	-
1.67	22.63	-	1,950	25.12	-
1.99	27.01	-	2,070	26.69	-
2.01	27.20	-	2,120	27.25	-
1.66	25.33	-	2,170	27.85	-
2.13	28.85	-	2,220	28.57	-
1.95	26.55	-	2,160	27.80	-
1.98	26.86	-	1,920	24.63	-
2.47	33.47	-	2,360	30.24	-
1.76	23.93	-	2,080	26.68	-
2.22	30.23	-	2,340	30.16	-
2.22	30.12	-	2,730	35.09	-
2.37	32.19	-	2,330	29.92	-
2.04	27.74	-	2,470	31.75	-
2.71	36.80	-	2,210	28.48	-
2.29	31.03	-	2,550	32.69	-
1.98	26.86	1,530	1,810	23.26	-
1.46	19.83	1,440	1,850	23.73	-
1.88	25.59	2,290	2,280	29.48	-
1.00	27.23	1,614	1,620	21.00	-
1.74	25.13	1,433	1,410	18.34	-
1.94	25.13	2,298	2,240	29.19	-
2.13	28.42	2,189	2,292	29.86	-
2.13	30.10	2,292	2,302	29.92	-
1.84	24.93	1,912	1,948	25.31	-
1.82	24.76	1,824	1,618	21.04	-
1.76	23.94	1,831	2,130	27.78	-
1.35	17.92	1,471	1,347	17.52	-
1.65	25.20	2,046	2,002	26.02	-
2.44	33.04	2,451	2,386	31.02	-
1.78	24.23	1,765	1,766	23.03	-
2.45	33.39	3,058	3,165	41.15	-
2.11	30.89	1,675	1,818	23.65	-
1.49	18.79	2,507	2,519	32.75	-
1.35	24.79	1,907	2,174	28.34	-
1.84	25.24	2,008	1,968	25.59	-
2.13	29.63	-	-	-	-

March 1930.  
Runoff, in inches, since March 1930.  
Natural runoff because of uncertainty in these figures are not published herein.

## 46. Hudson River at Spier Falls, N. Y.

Location.--Lat 43°14'29", long 73°44'50", on right bank 0.5 mile downstream from Spier Falls dam, 11 miles southwest of Glens Falls, Warren County, and about 11½ miles downstream from Sacandaga River.

Drainage area.--2,779 sq mi, revised. At site used prior to June 1, 1904, 2,817 sq mi (revised), and June 1, 1904, to Sept. 30, 1912, 2,755 sq mi (revised).

Gage.--Water stage recorder at present site and datum since October 1912. Datum of gage is 3.0 ft above mean low tide at New York City (levels by New York State Water Supply Commission). January 1899 to December 1908 staff gage at site about 14 miles downstream at different datum, and June 1904 to December 1912, staff gage about 7 miles upstream from described site at different datum.

Average discharge.--23 years (1899-1922), 5,391 cfs (unadjusted).

Extremes.--1912-22: Maximum discharge, 89,100 cfs Mar. 28, 1913 (gage height, 18.59 ft); minimum, about 6.5 cfs Sept. 23, 1917.

Remarks.--Stream affected by storage in Indian Lake and many small lakes and reservoirs in the upper part of the basin. Diurnal fluctuation caused by mills and powerplants at the station.

Cooperation.--Some gage heights, discharge measurements, and hourly discharges furnished by International Paper Co.

## Monthly and yearly mean discharge, in cubic feet per second

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1899	-	-	-	3,527	1,902	5,005	16,811	9,561	1,617	1,150	-	1,347	-
1900	1,033	5,098	5,157	3,211	17,074	3,934	16,914	6,358	2,834	1,248	1,652	1,110	4,595
1901	1,243	3,088	3,198	1,827	1,547	3,445	21,154	8,395	6,256	2,190	2,531	2,463	4,769
1902	2,679	2,138	4,771	2,422	2,218	13,316	7,060	4,692	5,493	7,204	4,743	2,466	4,949
1903	4,841	5,191	4,961	3,728	5,238	17,040	6,398	2,561	7,184	4,554	4,486	3,080	5,760
1904	6,691	3,733	3,545	4,889	3,403	7,009	16,030	10,250	5,520	2,460	3,030	2,890	5,787
1905	7,830	2,840	2,080	2,860	1,860	5,030	18,200	17,000	9,900	6,580	3,570	9,350	6,400
1906	4,340	4,730	4,790	6,400	3,950	4,580	16,200	10,400	6,120	3,880	2,020	1,870	5,770
1907	2,210	3,150	2,380	6,240	2,110	6,510	13,100	11,100	3,670	2,650	1,720	2,800	4,820
1908	6,220	10,200	7,710	5,320	6,070	9,630	19,600	16,300	2,760	1,840	*1,220	*933	*7,320
1909	*1,240	*1,560	*1,770	3,990	8,590	5,910	23,400	15,500	4,860	1,560	1,390	1,250	*5,870
1910	1,310	1,450	1,200	2,430	2,410	16,000	14,900	8,880	8,820	1,450	1,820	2,270	5,260
1911	2,420	2,740	1,540	2,640	2,040	2,790	14,700	*4,220	*1,770	*1,320	*1,830	-	*3,650
1912	*5,330	5,690	6,580	3,320	2,540	4,860	23,400	11,900	3,190	1,10	1,420	1,810	*5,130
1913	*5,380	6,260	4,920	8,580	2,980	21,100	12,300	5,460	3,350	1,200	978	933	*6,030
1914	2,080	5,150	2,390	1,590	1,710	2,750	24,400	9,680	1,650	1,800	1,510	1,770	4,750
1915	1,380	12,010	2,370	4,180	5,060	5,170	9,410	3,850	1,570	5,700	5,460	2,300	4,030
1916	2,890	3,030	3,200	5,330	6,430	4,940	18,000	12,300	4,990	2,510	1,430	1,520	5,540
1917	1,520	2,530	4,350	2,540	2,000	5,210	17,900	8,270	12,000	3,200	1,740	1,610	5,230
1918	3,350	4,870	2,040	1,580	2,320	7,680	19,100	8,710	3,680	1,930	1,450	2,310	4,920
1919	3,080	6,440	5,130	3,890	2,530	9,300	14,600	11,100	3,080	2,230	1,760	2,670	5,550
1920	3,920	6,090	4,060	2,210	1,830	6,710	20,900	7,460	2,410	2,220	2,040	1,610	5,110
1921	2,260	3,090	9,410	3,280	2,630	18,600	9,480	4,250	1,640	3,750	1,720	1,460	5,170
1922	1,730	4,280	4,410	2,260	2,640	2,210	23,700	3,900	10,100	5,030	2,340	1,950	6,370
1923	1,890	1,930	1,450	3,160	2,090	3,600	-	-	-	-	-	-	-

\* Only monthly figures revised; revised daily figures not published.

† Corrected.

\* Not previously published; partly estimated on basis of records for nearby stations.

## Yearly discharge, in cubic feet per second

Year	W.S.P. no.	Water year ending Sept. 30				Calendar year			
		Potentiary maximum		Minimum day	Mean	Per square mile	Runoff in inches	Mean	Runoff in inches
		Discharge	Date						
1899	47	-	-	-	-	-	-	-	-
1900	47	-	-	20	4,595	1.63	22.13	4,281	20.62
1901	65	-	-	20	4,769	1.69	23.01	4,950	23.89
1902	82	-	-	30	4,949	1.76	23.87	5,367	26.02
1903	125	-	-	360	5,780	2.05	27.85	5,687	27.45
1904	125	-	-	710	5,787	2.05	29.09	5,686	27.72
1905	301	-	-	1,790	6,400	2.32	31.14	6,400	31.19
1906	301	-	-	1,440	5,770	2.09	28.44	5,770	28.80
1907	301	-	-	1,360	4,820	1.75	23.73	6,190	30.50
1908	301	-	-	750	*7,320	*2.66	*36.20	*5,690	*28.14
1909	301	-	-	800	*5,870	*2.13	*28.94	*5,820	*28.69
1910	301	-	-	984	5,260	1.91	25.90	5,490	27.02
1911	301	-	-	1,000	*3,850	*1.40	*18.95	*4,940	*24.36
1912	321	-	-	1,110	*6,130	*2.23	*30.31	*5,692	*28.08
1913	351	89,100	Mar. 28, 1913	151	*6,030	*2.17	*29.48	5,670	27.71
1914	381	52,200	Apr. 21, 1914	401	4,750	1.71	23.19	4,380	21.38
1915	401	26,600	Apr. 13, 1915	467	4,030	1.45	119.71	4,320	21.12

\* Revised.

† Corrected.

\* Not previously published.

Published as "at Fort Edward," 1899-1908 (records to May 1904 used herein), as "at Corinth," June 1904 to December 1912 (records to September 1912 used herein), and "at Spier Falls" since October 1912.

## HUDSON RIVER BASIN

Yearly discharge, in cubic feet per second, of Hudson River at Spier Falls, N. Y.--Continued

Year	W.S.P. no.	Water year ending Sept. 30						Calendar year	
		Momentary maximum		Minimum day	Mean	Per square mile	Runoff in inches	Mean	Runoff in inches
		Discharge	Date						
1916	431	28,000	May 19, 1916	192	5,540	1.99	27.13	5,470	26.62
1917	451	30,100	June 12, 1917	506	5,230	1.88	25.57	5,380	26.31
1918	471	34,500	Apr. 4, 1918	606	4,920	1.77	24.07	5,360	26.20
1919	501	32,000	Apr. 13, 1919	722	5,550	2.00	27.19	5,450	26.22
1920	501	29,000	Apr. 1, 1920	335	5,110	1.84	25.05	5,150	25.37
1921	521	32,800	Mar. 22, 1921	419	5,170	1.86	25.26	4,800	23.45
1922	541	58,000	Apr. 13, 1922	523	6,370	2.23	31.14	5,940	29.03
1923	561	-	-	-	-	-	-	-	-

Note. Momentary maxima of discharge per square mile and runoff, in inches, previously published, may be subject to considerable error because of topographical errors in Indian lake and other small lakes and reservoirs in the basin. These figures are not published herein.

## 47. Glens Falls feeder at Glens Falls, N. Y.

Location.--Lat 43°17'30", long 73°39'55", on right bank at upstream end of feeder canal in City of Glens Falls, Warren County.

Gage.--Water-stage recorder. Datum of gage is at mean sea level (Barge Canal datum).

Auxiliary water-stage recorder 1,000 ft downstream from cement mill and 3.3 miles downstream from base gage.

Remarks.--Flow regulated in accordance with requirements of Champlain Canal and for floating logs. No diversion in winter months, during which periods the feeder may carry a small flow representing leakage through head gates.

Cooperation.--Records June 1919 to June 1921, and October 1924 to September 1925, not previously published by Geological Survey, furnished by State engineer and surveyor of New York.

Monthly mean discharge, in cubic feet per second

Year	May	June	July	Aug.	Sept.	Oct.	Nov.	
1919	-	223	203	228	271	261	-	
1920	-	248	242	237	247	275	-	
1921	-	205	-	-	-	-	-	
1924	-	-	-	-	-	230	-	
1925	-	188	193	-	191	-	-	
1927	-	204	208	221	206	161	148	
1928	163	161	176	203	229	210	194	
1929	134	187	229	233	233	193	-	
1930	146	152	178	184	203	188	-	
1931	145	178	195	203	163	150	-	
1932	-	132	180	166	162	140	155	
1933	137	135	126	140	167	164	198	
1934	143	131	151	154	162	196	181	
1935	159	129	122	152	155	150	130	
1936	171	160	159	152	170	173	190	
1937	168	166	157	175	191	183	184	
1938	160	150	159	156	171	187	-	
1939	-	137	130	139	156	161	-	
1940	-	159	169	168	202	207	-	
1941	157	152	156	162	168	191	-	
1942	133	169	183	190	180	187	189	
1943	188	164	139	138	161	167	177	
1944	135	118	134	139	159	162	160	
1945	124	130	134	135	152	147	458	
1946	-	107	105	99.3	77.9	73.6	80.4	
1947	147	113	131	170	180	186	184	
1948	162	145	142	154	163	175	173	
1949	140	133	141	131	140	140	131	
1950	-	-	-	-	-	-	-	

## 48. Glens Falls feeder at Dunham Basin, N. Y.

Location.--Lat 43°18'15", long 73°39'50", 100 ft upstream from Bond Brook, and 6 miles downstream from feeder dam at Glens Falls.

Gage.--Water-stage recorder. Datum of gage is 139.88 ft above mean sea level (Barge Canal datum).

Remarks.--Flow during navigation season is not diversion, through Glens Falls feeder, from the Hudson River basin to the summit level of the Champlain Division of the Barge Canal, and is regulated in accordance with requirements of the canal. Flow during remainder of year consists of leakage through head gates and runoff from area tributary to feeder above station. This flow may continue during period of no record.

Monthly mean discharge, in cubic feet

Year	Apr.	May
1945	-	-
1946	-	128
1947	-	94.1
1948	102	132
1949	-	144
1950	-	148

## 49. Bond Cr.

Location.--Lat 43°18'25", long 73°32' a quarter of a mile upstream from half a mile upstream from Barge mouth at Port Edward.

Drainage area.--14.7 sq mi.

Gage.--Water-stage recorder. Datum Canal datum.

Extremes.--1947-50. Maximum discharge minimum, 0.6 cfs Aug. 12, 1948.

Remarks.--During canal navigation season a mile below gage into Lake Champlain Dunham Basin.

Monthly and yearly

Water year	Oct.	Nov.	Dec.	Jan.	Feb.
1947	-	-	-	-	-
1948	1.23	4.71	4.17	2.43	18.6
1949	2.49	27.5	54.6	37.7	29.3
1950	2.84	9.94	20.7	32.2	13.6

Monthly

Water year	Oct.	Nov.	Dec.	Jan.	Feb.
1947	-	-	-	-	-
1948	0.10	0.36	0.33	0.19	1.36
1949	.20	2.08	4.29	2.98	2.07
1950	.22	.75	1.62	2.53	.96

Yearly discharge

Year	W.S.P. no.	Water	
		Momentary maximum	
		Discharge	Date
1947	1081	-	-
1948	1111	1,070	Mar. 20, 1948
1949	1141	1,370	Dec. 21, 1948
1950	1171	862	Mar. 25, 1950

## 50. East

Location.--Lat 43°04'40", long 73°01' highway 313 at Arlington, Vermont.

Drainage area.--152 sq mi.

Gage.--Water-stage recorder. Datum Prior to Nov. 18, 1941, drain gage

Average discharge.--22 years (1928-49)

Extremes.--1928-49. Maximum discharge minimum, 43 cfs Aug. 11, 1941.

Remarks.--Diurnal fluctuation at low

Published as Bond Brook at Dunham Basin

at Spier Falls, N. Y.--Continued

Per square mile	Runoff in inches	Calendar year	
		Mean	Runoff in inches
1.23	27.13	5,470	26.82
1.25	25.57	5,360	25.31
1.77	24.07	5,360	26.20
2.00	21.19	5,450	26.62
1.94	25.05	5,180	25.37
1.85	25.26	4,800	23.45
2.23	31.14	5,940	29.03

Falls, N. Y.

at upstream end of feeder canal

sea level (Barge Canal datum).

from cement mill and 3.3 miles down-

of Champlain Canal and for float-

in 1924 to September 1925, not pre-

State engineer and surveyor of New

Year	Sept.	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	Year
1947	1.23	4.71	1.23	2.43	18.6	9.1	2.4	16.2	16.0	23.5	3.31	1.55	-	-
1948	2.49	27.5	51.6	37.7	29.3	29.0	14.3	4.74	1.32	1.15	1.35	4.25	17.3	16.6
1949	2.84	9.34	20.7	32.2	13.6	1.2	25	5.63	5.25	1.39	1.97	4.29	16.2	16.2
1950	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1951	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1952	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1953	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1954	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1955	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1956	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1957	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1958	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1959	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1960	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1961	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1962	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1963	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1964	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1965	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1966	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1967	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1968	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1969	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1970	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1971	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1972	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1973	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1974	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1975	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1976	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1977	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1978	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1979	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1980	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1981	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1982	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1983	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1984	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1985	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1986	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1987	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1988	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1989	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1990	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1991	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1992	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1993	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1994	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1995	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1996	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1997	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1998	-	-	-	-	-	-	-	-	-	-	-	-	-	-
1999	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2000	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2001	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2002	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2003	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2004	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2005	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2006	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2007	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2008	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2009	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2010	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2011	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2012	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2013	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2014	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2015	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2016	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2017	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2018	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2019	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2020	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2021	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2022	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2023	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2024	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2025	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2026	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2027	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2028	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2029	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2030	-	-	-	-	-	-	-	-	-	-	-	-	-	-

Basin, N. Y.

at Dunham Basin, Washington County,

from feeder dam at Glens Falls.

above mean sea level (Barge

in, through Glens Falls feeder,  
the Champlain Division of the Barge  
into of the canal. Flow during  
times and runoff from area tribu-  
during period of no record.

Monthly mean discharge, in cubic feet per second, of Glens Falls feeder at Dunham Basin, N. Y.

Year	Apr.	May	June	July	Aug.	Sept.	Oct.	Nov.
1945	-	-	-	-	-	-	139	149
1946	-	128	92.3	79.2	75.2	56.3	59.7	69.2
1947	-	94.1	107	96.6	125	149	166	173
1948	102	132	116	120	109	113	143	162
1949	-	144	109	101	111	117	137	155
1950	-	128	102	95.0	94.0	99.3	119	126

49. Bond Creek at Dunham Basin, N. Y.1/

a quarter of a mile upstream from the dam at Dunham Basin, Champlain Division, and half a mile upstream from Barge Canal (Champlain Division), and 4 miles upstream from mouth at Fort Edward.

Drainage area--14.7 sq mi.

Gage--Water-stage recorder. Datum of gage is 140.30 ft above mean sea level (Barge Canal datum).

Extremes--1947-50: Maximum discharge, 1,370 cfs Dec. 31, 1948 (gage height, 8.52 ft); minimum, 0.6 cfs Aug. 11, 13, 1949 (gage height, 1.73 ft).

Remarks--During canal navigation season, a portion of the flow is diverted at point half a mile below gage into Lake Champlain basin through summit level of Champlain Canal at Dunham Basin.

Monthly and yearly mean discharge, in cubic feet per second

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1947	-	-	-	-	-	-	-	-	-	23.5	3.31	1.55	-
1948	1.23	4.71	2.43	18.6	9.1	2.4	16.2	16.0	23.5	3.31	1.55	16.6	16.6
1949	2.49	27.5	51.6	37.7	29.3	29.0	14.3	4.74	1.32	1.15	1.35	4.25	17.3
1950	2.84	9.34	20.7	32.2	13.6	1.2	25	5.63	5.25	1.39	1.97	4.29	16.2

Monthly and yearly runoff, in inches

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1947	-	-	-	-	-	-	-	-	-	1.83	0.26	0.12	-
1948	0.10	0.36	0.33	0.19	1.36	7.14	2.08	1.27	1.21	1.77	.43	.11	15.35
1949	.20	2.08	4.29	2.95	2.07	2.28	1.11	.37	.10	.09	.12	.32	15.98
1950	.22	.75	1.62	2.53	.96	5.59	1.93	.45	.25	.16	.15	.33	14.94

Yearly discharge, in cubic feet per second

Year	W.S.P. no.	Water year ending Sept. 30				Calendar year			
		Foretary maximum		Minimum day	Mean	Per square mile	Runoff in inches	Year	Runoff in inches
		Discharge	Date						
1947	1081	-	-	-	-	-	-	-	-
1948	1111	1,070	Mar. 20, 1948	1.0	16.6	1.13	15.35	22.8	21.12
1949	1141	1,370	Dec. 31, 1948	.6	17.3	1.18	15.98	13.0	12.01
1950	1171	862	Mar. 28, 1950	1.0	16.2	1.10	14.94	-	-

50. Batten Hill at Arlington, Vt.

Location--Lat 42°54'40", Long 72°51'50". Gage is 5 ft upstream from bridge at Batten Hill.

Drainage area--14.7 sq mi.

Gage--Water-stage recorder. Datum of gage is 537.68 ft above mean sea level, unadjusted. Prior to Nov. 18, 1941, chain gage at downstream side of bridge at same datum.

Average discharge--22 years (1928-50), 338 cfs.

Extremes--1928-50: Maximum discharge, 11,100 cfs Mar. 18, 1936 (gage height, 11.3 ft, present site, from floodmarks), from rating curve extended above 5,200 cfs on basis of slope-area determination at gage height 10.8 ft and computation of peak flow over dam; minimum observed, 43 cfs Aug. 11, 1939.

Remarks--Diurnal fluctuation at low flow caused by mill at Batten Hill.

1/ Published as Bond Brook at Dunham Basin prior to October 1950.

## 3270. Glens Falls feeder at Glens Falls, N. Y.

Location.--Lat 43°17'30", long 73°39'55", on right bank at upstream end of feeder canal in city of Glens Falls, Warren County.

Records available.--June 1919 to October 1920, June 1921, October 1924, June, July, September, 1925, June 1927 to September 1960 (navigation seasons only). Monthly discharge only for some periods, published in WSP 1302.

Gage.--Water-stage recorder. Datum of gage is at mean sea level (Barge Canal datum).

Remarks.--Flow regulated in accordance with requirements of Champlain (Barge) Canal and for floating logs. No diversion in winter months, during which periods the feeder may carry a small flow representing leakage through headgates.

Correction.--In WSP 1302 the monthly mean discharge for November 1945 is listed in error; it should be 159 cfs.

Monthly mean discharge, in cubic feet per second

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1951	140	131	-	-	-	-	-	130	135	145	152	139	-
1952	170	144	-	-	-	-	-	127	146	150	153	-	-
1953	160	155	-	-	-	-	-	111	155	139	137	148	-
1954	148	145	-	-	-	-	-	126	137	168	152	142	-
1955	152	-	-	-	-	-	-	-	131	144	137	140	-
1956	160	-	-	-	-	-	-	136	139	158	155	151	-
1957	140	179	-	-	-	-	-	133	147	135	140	131	-
1958	160	146	-	-	-	-	-	175	140	133	121	124	-
1959	122	139	-	-	-	-	-	126	133	143	117	136	-
1960	166	130	-	-	-	-	-	135	142	124	126	141	-

## 3275. Glens Falls feeder at Dunham Basin, N. Y.

Location.--Lat 43°18'15", long 73°32'50", on left bank at Dunham Basin, Washington County, 100 ft upstream from Bond Creek and 8 miles downstream from feeder dam at Glens Falls.

Records available.--September 1945 to September 1960 (navigation seasons only).

Gage.--Water-stage recorder. Datum of gage is 139.88 ft above mean sea level (Barge Canal datum).

Remarks.--Flow during navigation season is net diversion through Glens Falls feeder, from the Hudson River basin to the summit level of the Champlain (Barge) Canal, and is regulated in accordance with requirements of the canal. Flow during remainder of year consists of leakage through headgates and runoff from area tributary to feeder above station. This flow may continue during period of no record.

Monthly mean discharge, in cubic feet per second

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1951	119	126	-	-	-	-	91.2	111	107	99.5	118	110	-
1952	153	144	-	-	-	-	-	131	124	128	131	126	-
1953	143	153	-	-	-	-	-	110	109	94.4	108	112	-
1954	122	129	-	-	-	-	113	122	115	113	103	108	-
1955	126	155	-	-	-	-	-	99.8	100	104	92.7	115	-
1956	166	178	-	-	-	-	-	134	127	127	125	130	-
1957	129	166	-	-	-	-	-	120	94.8	98.6	98.9	98.3	-
1958	136	133	-	-	-	-	-	158	125	100	84.3	87.6	-
1959	109	131	-	-	-	-	-	128	110	105	84.0	100	-
1960	134	126	-	-	-	-	-	134	109	71.7	76.5	107	-

## 3280. Bond Creek at D

Location.--Lat 43°18'25", long 73°32'55", on 1 County, a quarter of a mile upstream from G Canal, half a mile upstream from Champlain mouth at Fort Edward.

Drainage area.--14.7 sq mi.

Records available.--June 1947 to September 1960 Bond Brook at Dunham Basin.

Gage.--Water-stage recorder. Datum of gage is Canal datum).

Average discharge.--13 years (1947-60), 18.2 c

Extremes.--1947-60: Maximum discharge, 1,370 minimum, 0.4 cfs July 18, 19, 1959.

Remarks.--During canal navigation season, a p half a mile below gage into Lake Champlain (Barge) Canal at Dunham Basin.

Monthly and yearly mean discharge

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.
1951	1.83	9.06	23.6	15.4	62.9	57.0	57.0
1952	14.8	36.1	33.0	42.7	29.1	67.7	46
1953	3.22	5.51	32.9	27.9	41.2	59.0	36
1954	1.66	1.81	11.1	9.08	60.4	34.3	31
1955	1.99	21.5	19.7	3.94	35.4	70.3	31
1956	42.8	31.0	7.07	9.10	4.06	17.6	31
1957	3.34	5.43	10.9	22.6	15.3	22.9	31
1958	2.17	10.1	49.1	25.6	7.98	10.7	31
1959	5.58	8.46	7.63	15.4	8.34	17.1	31
1960	4.85	36.0	30.7	21.0	32.5	26.3	31


Monthly and yearly mean discharge

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.
1951	0.14	0.69	1.85	1.21	4.46	4.67	4.67
1952	1.16	2.74	2.59	3.35	2.14	5.31	4.63
1953	.25	.42	2.58	2.19	2.92	2.69	2.69
1954	.13	.14	.87	.71	4.28	5.31	5.31
1955	.16	1.63	1.54	.31	2.51	5.31	5.31
1956	3.56	2.35	.55	.71	.30	1.40	1.40
1957	.26	.41	.86	1.77	1.08	1.78	1.78
1958	.17	.77	3.85	2.01	.57	5.55	5.55
1959	.44	.64	.60	1.21	.59	1.54	1.54
1960	.38	2.73	2.41	1.65	2.38	2.06	2.06

Yearly discharge, :

Year	WSP	Water year end		
		Momentary maximum		Minimum day
		Discharge	Date	
1950	-	-	-	-
1951	1202	450	Feb. 21, 1951	1
1952	1232	1,240	June 1, 1952	1
1953	1272	823	Feb. 21, 1953	1
1954	1332	745	June 1, 1954	1
1955	1382	626	Mar. 1, 1955	1
1956	1432	1,020	Apr. 5, 1956	1
1957	1502	622	Jan. 23, 1957	1
1958	1552	956	Dec. 21, 1957	1
1959	1622	734	Apr. 2, 1959	1
1960	1702	762	Nov. 28, 1959	1

HUDSON RIVER ABOVE FLEDERHAM - GLENS FALLS - GAUGE #127



U.S. GEOLOGICAL SURVEY



HUDSON RIVER

ABOVE FLECKER DAM - GLENS FALLS - GAUGE # 127

1936 1938 1940 1942 1944 1946 1948 1950 1952 1954 1956

292 +

290 +


288 +

286 +

284 +

282 +

280 +



HUDSON RIVER ABOVE FEEDER DAM-GLENS FALLS-GAUGE # 127

1256 1258 1260 1262 1264 1266 1268 1270 1272 1274 1276


292 +	+	+	+	+	+	+	+	+	+	+
290 +	+	+	+	+	+	+	+	+	+	+
288 +	+	+	+	+	+	+	+	+	+	+
286 +	+	+	+	+	+	+	+	+	+	+
284 +	+	+	+	+	+	+	+	+	+	+
282 +	+	+	+	+	+	+	+	+	+	+
280 +	+	+	+	+	+	+	+	+	+	+

288.05  
GAUGE DISCONTINUED

APPENDIX E

STRUCTURAL STABILITY ANALYSES

丁  
 一  
 五  
 二  
 井



PROJECT GRID

JOB	SHEET NO.	CHECKED BY	DATE
FEEDER DAM AT GLEN FALLS	1		
SUBJECT	COMPUTED BY	DATE	
SEISMIC STABILITY ANALYSIS	RLW	6/1/77	

SUMMATIONS OF MOMENTS AND FORCES TAKEN FROM  
CALCULATOR STABILITY PROGRAM

NORMAL CONDITIONS - WATER AT SPILLWAY CREST - NO ICE

1. CALCULATE HORIZONTAL FORCE ON UPSTREAM FACE DUE  
TO WATER PRESSURE

$$P_w = C \times W \times h = .7(.11)(.0624)(26) = .113 \text{ K/ft}^2$$

$P_w$  = WATER PRESSURE  
 $C$  = COEFFICIENT  
 $W$  = WGT. OF WATER  
 $h$  = height

$$V_w = .726 P_w y = .726(.113)(26) = 2.14 \text{ K}$$

2. CALCULATE MOMENT

$$M_w = .299 P_w y^2 = .299(.113)(26)^2 = 22.84 \text{ K-ft}$$

3. REDUCE WEIGHT OF CONCRETE BY 5%

$$(.115)(.95) = .109$$

4. REVISED OVERTURNING SAFETY FACTOR

$$F.S. = \frac{\text{RESISTING MOMENTS}}{\text{OVERTURNING MOMENTS + EARTHQUAKE MOM.}} = \frac{27465.2}{1312 + 22.8} = 20.58$$

PROJECT GRID

JOB FELDER DAM AT GLEN'S FALLS	SHEET NO. 2	CHECKED BY	DATE
SUBJECT SEISMIC STABILITY ANALYSIS		COMPUTED BY RLW	DATE 3/1/79
5 REVISED SLIDING SAFETY FACTOR			
$F.S. = \frac{\text{RESISTING FORCE}}{\text{SLIDING FORCE} + \text{EARTHQUAKE FORCE}} = \frac{13575.73}{35535 + 2.14} = 37.97$			

# NORMAL CONDITIONS w/ KEY

0.15	RCL
	1
104.	
104.	RCL
	2
26.3	
26.3	RCL
	3
170.5	
170.5	RCL
	4
19.2	
19.2	RCL
	5
26.4	
26.4	RCL
	6
4.4	
4.4	RCL
	7
28.3	
28.3	RCL
	8
26.	
26.	RCL
	9
0.	
0.	RCL
	10
0.6	
0.6	RCL
	11
130.	
130.	RCL
	12
0.17	
0.17	RCL
	13
5.8	
5.8	RCL
	14
0.	
0.	RCL
	15
5.5	
5.5	RCL
	16
6.	
0.	RCL
	17
10.	
10.	RCL
	18
0.0624	
0.0624	RCL
	46
26.	

# NORMAL CONDITIONS

PLUS ICE	w/ KEY
0.15	RCL
104.	
104.	RCL
	2
26.3	
26.3	RCL
	3
170.5	
170.5	RCL
	4
19.2	
19.2	RCL
	5
26.4	
26.4	RCL
	6
4.4	
4.4	RCL
	7
28.3	
28.3	RCL
	8
26.	
26.	RCL
	9
10.	
10.	RCL
	10
0.6	
0.6	RCL
	11
130.	
130.	RCL
	12
0.17	
0.17	RCL
	13
5.8	
5.8	RCL
	14
0.	
0.	RCL
	15
5.5	
5.5	RCL
	16
6.	
6.	RCL
	17
10.	
10.	RCL
	18
0.0624	
0.0624	RCL
	18
0.0624	
0.0624	RCL
	46
26.	

## FACTORS OF SAFETY

21.39090591	← OVERTURNING →	17.8580199
38.20425112	← SLIDING →	17.1190252

3

NORMAL CONDITIONS  
w/ KEY  
(SEISMIC ANALYSIS)

0.109	PCL
	1
.04.	
.04.	PCL
	2
26.3	
26.3	PCL
	3
170.5	
170.5	PCL
	4
0.	
0.	PCL
	5
26.4	
26.4	PCL
	6
4.4	
4.4	PCL
	7
28.3	
28.3	PCL
	8
26.	
26.	PCL
	9
0.	
0.	PCL
	10
0.6	
0.6	PCL
	11
130.	
130.	PCL
	12
0.17	
0.17	PCL
	13
5.8	
5.8	PCL
	14
0.	
0.	PCL
	15
5.5	
5.5	PCL
	16
6.	
6.	PCL
	17
10.	
10.	PCL
	18
0.0624	
0.0624	PCL
	46
36.	

FACTORS OF SAFETY

OVERTURNING	20.93053928
	25854.81482
SLIDING	38.20042077



1/2 PMF w/KEY

1/2 PMF wo/KEY

0.15 RCL  
1  
104.  
104. RCL  
2  
26.3  
26.3 RCL  
3  
170.5  
170.5 RCL  
4  
19.2  
19.2 RCL  
5  
26.4  
26.4 RCL  
6  
4.4  
4.4 RCL  
7  
28.3  
28.3 RCL  
8  
26.  
26. RCL  
9  
0.  
0. RCL  
10  
0.6  
0.6 RCL  
11  
130.  
130. RCL  
12  
0.17  
0.17 RCL  
13  
5.8  
5.8 RCL  
14  
15.  
15. RCL  
15  
5.5  
5.5 RCL  
16  
6.  
6. RCL  
17  
10.  
10. RCL  
18  
0.0624  
0.0624 RCL  
46  
26.

0.15 RCL  
1  
88.  
88. RCL  
2  
26.3  
26.3 RCL  
3  
170.5  
170.5 RCL  
4  
19.2  
19.2 RCL  
5  
26.4  
26.4 RCL  
6  
4.4  
4.4 RCL  
7  
28.3  
28.3 RCL  
8  
22.  
22. RCL  
9  
0.  
0. RCL  
10  
0.6  
0.6 RCL  
11  
130.  
130. RCL  
12  
0.17  
0.17 RCL  
13  
5.8  
5.8 RCL  
14  
15.  
15. RCL  
15  
1.5  
1.5 RCL  
16  
1.7  
1.7 RCL  
17  
6.  
6. RCL  
18  
0.0624  
0.0624 RCL  
19  
0.  
0. RCL  
46  
22.

FACTORS OF SAFETY

14.9-632064  
~~251777.9837~~  
35.75335971

OVERTURNING

SLIDING

1.452005353  
~~0.0624~~  
16.05810279

APPENDIX F

REFERENCES

## REFERENCES

- 1) US Army Corps of Engineers; New York District; Upper Hudson and Mohawk River Basins Hydrologic Flood Routing Models, October 1976.
- 2) US Geological Survey; Compilation of Records of Surface Waters of the United States, Part 1-B North Atlantic Slope Basins;

Water Supply Paper 1302 (Through September 1950), 1960.

Water Supply Paper 1722 (October 1950 to September 1960), 1964.

- 3) H.W. King and E.F. Brater; Handbook of Hydraulics, 5th edition, McGraw - Hill, 1963.
- 4) E.E. Seelye; Design, 3rd edition, John Wiley and Sons, Inc., 1960.
- 5) University of the State of New York; Geology of New York, Education Leaflet 20, Reprinted 1973.
- 6) U.S. Department of the Interior, Bureau of Reclamation; Design of Small Dams, 2nd edition (rev. reprint), 1977.

APPENDIX G  
CORPS OF ENGINEERS  
GUIDELINES

Reclamation and Soil Conservation Service. Many other agencies, educational facilities and private consultants can also provide expert advice. Regardless of where such expertise is based, the qualification of those individuals offering to provide it should be carefully examined and evaluated.

4.3.4. Freeboard Allowances. Guidelines on specific minimum freeboard allowances are not considered appropriate because of the many factors involved in such determinations. The investigator will have to assess the critical parameters for each project and develop its minimum requirement. Many projects are reasonably safe without freeboard allowance because they are designed for overtopping, or other factors minimize possible overtopping. Conversely, freeboard allowances of several feet may be necessary to provide a safe condition. Parameters that should be considered include the duration of high water levels in the reservoir during the design flood; the effective wind fetch and reservoir depth available to support wave generation; the probability of high wind speed occurring from a critical direction; the potential wave runup on the dam based on roughness and slope; and the ability of the dam to resist erosion from overtopping waves.

4.4. Stability Investigations. The Phase II stability investigations should be compatible with the guidelines of this paragraph.

4.4.1. Foundation and Material Investigations. The scope of the foundation and materials investigation should be limited to obtaining the information required to analyze the structural stability and to investigate any suspected condition which would adversely affect the safety of the dam. Such investigations may include borings to obtain concrete, embankment, soil foundation, and bedrock samples; testing specimens from these samples to determine the strength and elastic parameters of the materials, including the soft seams, joints, fault gouge and expansive clays or other critical materials in the foundation; determining the character of the bedrock including joints, bedding planes, fractures, faults, voids and caverns, and other geological irregularities; and installing instruments for determining movements, strains, suspected excessive internal seepage pressures, seepage gradients and uplift forces. Special investigations may be necessary where suspect rock types such as limestone, gypsum, salt, basalt, claystone, shales or others are involved in foundations or abutments in order to determine the extent of cavities, piping or other deficiencies in the rock foundation. A concrete core drilling program should be undertaken only when the existence of significant structural cracks is suspected or the general qualitative condition of the concrete is in doubt. The tests of materials will be necessary only where such data are lacking or are outdated.

4.4.2. Stability Assessment. Stability assessments should utilize in situ properties of the structure and its foundation and pertinent geologic

information. Geologic information that should be considered includes groundwater and seepage conditions; lithology, stratigraphy, and geologic details disclosed by borings, "as-built" records, and geologic interpretation; maximum past overburden at site as deduced from geologic evidence; bedding, folding and faulting; joints and joint systems; weathering; slickensides, and field evidence relating to slides, faults, movements and earthquake activity. Foundations may present problems where they contain adversely oriented joints, slickensides or fissured material, faults, seams of soft materials, or weak layers. Such defects and excess pore water pressures may contribute to instability. Special tests may be necessary to determine physical properties of particular materials. The results of stability analyses afford a means of evaluating the structure's existing resistance to failure and also the effects of any proposed modifications. Results of stability analyses should be reviewed for compatibility with performance experience when possible.

4.4.2.1. Seismic Stability. The inertial forces for use in the conventional equivalent static force method of analysis should be obtained by multiplying the weight by the seismic coefficient and should be applied as a horizontal force at the center of gravity of the section or element. The seismic coefficients suggested for use with such analyses are listed in Figures 1 through 4. Seismic stability investigations for all high hazard category dams located in Seismic Zone 4 and high hazard dams of the hydraulic fill type in Zone 3 should include suitable dynamic procedures and analyses. Dynamic analyses for other dams and higher seismic coefficients are appropriate if in the judgment of the investigating engineer they are warranted because of proximity to active faults or other reasons. Seismic stability investigations should utilize "state-of-the-art" procedures involving seismological and geological studies to establish earthquake parameters for use in dynamic stability analyses and, where appropriate, the dynamic testing of materials. Stability analyses may be based upon either time-history or response spectra techniques. The results of dynamic analyses should be assessed on the basis of whether or not the dam would have sufficient residual integrity to retain the reservoir during and after the greatest or most adverse earthquake which might occur near the project location.

4.4.2.2. Clay Shale Foundation. Clay shale is a highly overconsolidated sedimentary rock comprised predominantly of clay minerals, with little or no cementation. Foundations of clay shales require special measures in stability investigations. Clay shales, particularly those containing montmorillonite, may be highly susceptible to expansion and consequent loss of strength upon unloading. The shear strength and the resistance to deformation of clay shales may be quite low and high pore water pressures may develop under increase in load. The presence of slickensides in clay shales is usually an indication of low shear strength. Prediction

of field behavior of clay shales should not be based solely on results of conventional laboratory tests since they may be misleading. The use of peak shear strengths for clay shales in stability analyses may be unconservative because of nonuniform stress distribution and possible progressive failures. Thus the available shear resistance may be less than if the peak shear strength were mobilized simultaneously along the entire failure surface. In such cases, either greater safety factors or residual shear strength should be used.

#### 4.4.3. Embankment Dams.

4.4.3.1. Liquefaction. The phenomenon of liquefaction of loose, saturated sands and silts may occur when such materials are subjected to shear deformation or earthquake shocks. The possibility of liquefaction must presently be evaluated on the basis of empirical knowledge supplemented by special laboratory tests and engineering judgment. The possibility of liquefaction in sands diminishes as the relative density increases above approximately 70 percent. Hydraulic fill dams in Seismic Zones 3 and 4 should receive particular attention since such dams are susceptible to liquefaction under earthquake shocks.

4.4.3.2. Shear Failure. Shear failure is one in which a portion of an embankment or of an embankment and foundation moves by sliding or rotating relative to the remainder of the mass. It is conventionally represented as occurring along a surface and is so assumed in stability analyses, although shearing may occur in a zone of substantial thickness. The circular arc or the sliding wedge method of analyzing stability, as pertinent, should be used. The circular arc method is generally applicable to essentially homogeneous embankments and to soil foundations consisting of thick deposits of fine-grained soil containing no layers significantly weaker than other strata in the foundation. The wedge method is generally applicable to rockfill dams and to earth dams on foundations containing weak layers. Other methods of analysis such as those employing complex shear surfaces may be appropriate depending on the soil and rock in the dam and foundation. Such methods should be in reputable usage in the engineering profession.

4.4.3.3. Loading Conditions. The loading conditions for which the embankment structures should be investigated are (I) Sudden drawdown from spillway crest elevation or top of gates, (II) Partial pool, (III) Steady state seepage from spillway crest elevation or top of gate elevation, and (IV) Earthquake. Cases I and II apply to upstream slopes only; Case III applies to downstream slopes; and Case IV applies to both upstream and downstream slopes. A summary of suggested strengths and safety factors are shown in Table 4.

4.4.3.6. Seepage Analyses. Review and modifications to original seepage design analyses should consider conditions observed in the field inspection and piezometer instrumentation. A seepage analysis should consider the permeability ratios resulting from natural deposition and from compaction placement of materials with appropriate variation between horizontal and vertical permeability. An underseepage analysis of the embankment should provide a critical gradient factor of safety for the maximum head condition of not less than 1.5 in the area downstream of the embankment.

$$F.S = i_c/i = \frac{H_c/D_b}{H'/D_b} = D_b \frac{(\gamma_m - \gamma_w)}{H \gamma_w} \quad (2)$$

$i_c$  = Critical gradient

$i$  = Design gradient

$H$  = Uplift head at downstream toe of dam measured above tailwater

$H_c$  = The critical uplift

$D_b$  = The thickness of the top impervious blanket at the downstream toe of the dam

$\gamma_m$  = The estimated saturated unit weight of the material in the top impervious blanket

$\gamma_w$  = The unit weight of water

Where a factor of safety less than 1.5 is obtained the provision of a underseepage control system is indicated. The factor of safety of 1.5 is a recommended minimum and may be adjusted by the responsible engineer based on the competence of the engineering data.

#### 4.4.4. Concrete Dams and Appurtenant Structures.

4.4.4.1. Requirements for Stability. Concrete dams and structures appurtenant to embankment dams should be capable of resisting overturning, sliding and overstressing with adequate factors of safety for normal and maximum loading conditions.



4.4.4.2. Loads. Loadings to be considered in stability analyses include the water load on the upstream face of the dam; the weight of the structure; internal hydrostatic pressures (uplift) within the body of the dam, at the base of the dam and within the foundation; earth and silt loads; ice pressure, seismic and thermal loads, and other loads as applicable. Where tailwater or backwater exists on the downstream side of the structure it should be considered, and assumed uplift pressures should be compatible with drainage provisions and uplift measurements if available. Where applicable, ice pressure should be applied to the contact surface of the structure at normal pool elevation. A unit pressure of not more than 5,000 pounds per square foot should be used. Normally, ice thickness should not be assumed greater than two feet. Earthquake forces should consist of the inertial forces due to the horizontal acceleration of the dam itself and hydrodynamic forces resulting from the reaction of the reservoir water against the structure. Dynamic water pressures for use in conventional methods of analysis may be computed by means of the "Westergaard Formula" using the parabolic approximation (H.M. Westergaard, "Water Pressures on Dams During Earthquakes," Trans., ASCE, Vol 98, 1933, pages 418-433), or similar method.

4.4.4.3. Stresses. The analysis of concrete stresses should be based on in situ properties of the concrete and foundation. Computed maximum compressive stresses for normal operating conditions in the order of  $1/3$  or less of in situ strengths should be satisfactory. Tensile stresses in unreinforced concrete should be acceptable only in locations where cracks will not adversely affect the overall performance and stability of the structure. Foundation stresses should be such as to provide adequate safety against failure of the foundation material under all loading conditions.

4.4.4.4. Overturning. A gravity structure should be capable of resisting all overturning forces. It can be considered safe against overturning if the resultant of all combinations of horizontal and vertical forces, excluding earthquake forces, acting above any horizontal plane through the structure or at its base is located within the middle third of the section. When earthquake is included the resultant should fall within the limits of the plane or base, and foundation pressures must be acceptable. When these requirements for location of the resultant are not satisfied the investigating engineer should assess the importance to stability of the deviations.

4.4.4.5. Sliding. Sliding of concrete gravity structures and of abutment and foundation rock masses for all types of concrete dams should be evaluated by the shear-friction resistance concept. The available sliding resistance is compared with the driving force which tends to induce sliding to arrive at a sliding stability safety factor. The investigation should be made along all potential sliding paths. The critical path is that plane or combination of planes which offers the least resistance.

4.4.4.3.1. Sliding Resistance. Sliding resistance is a function of the unit shearing strength at no normal load (cohesion) and the angle of friction on a potential failure surface. It is determined by computing the maximum horizontal driving force which could be resisted along the sliding path under investigation. The following general formula is obtained from the principles of statics and may be derived by resolving forces parallel and perpendicular to the sliding plane:

$$R_R = V \tan (\phi + \alpha) + \frac{cA}{\cos \alpha (1 - \tan \phi \tan \alpha)} \quad (3)$$

where

$R_R$  = Sliding Resistance (maximum horizontal driving force which can be resisted by the critical path)

$\phi$  = Angle of internal friction of foundation material or, where applicable, angle of sliding friction

$V$  = Summation of vertical forces (including uplift)

$c$  = Unit shearing strength at zero normal loading along potential failure plane

$A$  = Area of potential failure plane developing unit shear strength "c"

$\alpha$  = Angle between inclined plane and horizontal (positive for uphill sliding)

For sliding downhill the angle  $\alpha$  is negative and Equation (1) becomes:

$$R_R = V \tan (\phi - \alpha) + \frac{cA}{\cos \alpha (1 + \tan \phi \tan \alpha)} \quad (4)$$

When the plane of investigation is horizontal, and the angle  $\alpha$  is zero and Equation (1) reduced to the following:

$$R_R = V \tan \phi + cA \quad (5)$$

4.4.4.5.2. Downstream Resistance. When the base of a concrete structure is embedded in rock or the potential failure plane lies below the base, the passive resistance of the downstream layer of rock may sometimes be utilized for sliding resistance. Rock that may be subjected to high velocity water scouring should not be used. The magnitude of the downstream resistance is the lesser of (a) the shearing resistance along the continuation of the potential sliding plane until it daylights or (b) the resistance available from the downstream rock wedge along an inclined plane. The theoretical resistance offered by the passive wedge can be computed by a formula equivalent to formula (3):

$$P_p = W \tan (\phi + \alpha) + \frac{cA}{\cos \alpha (1 - \tan \phi \tan \alpha)} \quad (6)$$

$P_p$  = passive resistance of rock wedge

$W$  = weight (buoyant weight if applicable) of downstream rock wedge above inclined plane of resistance, plus any superimposed loads

$\phi$  = angle of internal friction or, if applicable, angle of sliding friction

$\alpha$  = angle between inclined failure plane and horizontal

$c$  = unit shearing strength at zero normal load along failure plane

$A$  = area of inclined plane of resistance

When considering cross-bed shear through a relatively shallow, competent rock strut, without adverse jointing or faulting,  $W$  and  $\alpha$  may be taken at zero and  $45^\circ$ , respectively, and an estimate of passive wedge resistance per unit width obtained by the following equation:

$$P_p = 2 cD \quad (7)$$

where

$D$  = Thickness of the rock strut

4.4.4.5.3. Safety Factor. The shear-friction safety factor is obtained by dividing the resistance  $R_R$  by  $H$ , the summation of horizontal service

loads to be applied to the structure:

$$S_{s-f} = \frac{R_R}{H} \quad (8)$$


When the downstream passive wedge contributes to the sliding resistance, the shear friction safety factor formula becomes:

$$S_{s-f} = \frac{R_R + P_p}{H} \quad (9)$$

The above direct superimposition of passive wedge resistance is valid only if shearing rigidities of the foundation components are similar. Also, the compressive strength and buckling resistance of the downstream rock layer must be sufficient to develop the wedge resistance. For example, a foundation with closely spaced, near horizontal, relatively weak seams might not contain sufficient buckling strength to develop the magnitude of wedge resistance computed from the cross-bed shear strength. In this case wedge resistance should not be assumed without resorting to special treatment (such as installing foundation anchors). Computed sliding safety factors approximating 3 or more for all loading conditions without earthquake, and 1.5 including earthquake, should indicate satisfactory stability, depending upon the reliability of the strength parameters used in the analyses. In some cases when the results of comprehensive foundation studies are available, smaller safety factors may be acceptable. The selection of shear strength parameters should be fully substantiated. The bases for any assumptions; the results of applicable testing, studies and investigations; and all pre-existing, pertinent data should be reported and evaluated.


APPENDIX H

DRAWINGS




VICINITY MAP

FEEDER DAM @ GLENS FALLS




# FEEDER DAM @ GLENS FALLS (NOT TO SCALE)

PERTINENT FEATURES OF THE FEEDER DAM @ GLENS FALLS








GEO. FREEMAN

GEO. FREEMAN



184000

392+04.39

393+02.39


APPROXIMATE BLUE LINE

GLEN'S


APPROXIMATE


BLUE LINE

SPARK BRK CR 864.51



Woods





For 50'

195'

199'

195'




Made by, Traced from  
Checked by, mounted map  
Traced by, Cosgrave.  
2nd. Check by.

5

EXCAVATION FROM  
Dam, bulkheads and prism sta. 370 to Hudson River

GE

HUDSON



$El. 260.07$   
TYPICAL SECTION STA. 373+00. TO STA. 398+  
Scale:  $1" = 20'$

PLAN  
Scale:  $1" = 100'$

FREEMAN

ROCK

RIVER →

bankment with gravel lining on top.  
lining not over 12" thick

**Contract**  
**Champlain Canal**  
Glens Falls  
**PLAN & TYPE**  
**STA. 372+00 TO**  
Scale

Examined and approved

*July 1, 1952*  
*E. F. [Signature]*  
Sponsoring Engineer

# Contract No. 56.

Plain Canal                      Section 2  
Glens Falls Feeder

PLAN & TYPICAL SECTIONS  
A. 372+00 TO HUDSON RIVER


Scales as indicated

Approved

Examined and approved

*F. H. [Signature]*  
Engineer

*July 1, 1912*  
*Alvin S. [Signature]*  
Special Deputy State Engineer



El. 294.5



For details of  
see Sheet #5

Existing dam and piers to be removed to Elev 276.0

Present Dam

20'

20'

175'

LAYOUT OF DAM AND BULKHEADS

Scale: 1" = 50' 0"

Old Suu

2

E1.290.07

North Bulkhead

For details of By-Pass.  
see Sheet # 26

By-Pass


Lock # 1

Lumber Conveyor


Mill

Lumber Conveyor


Cap to be made of  
Cast Iron 5" diam  
3/4" thick, To be screwed  
to a 2 1/2" Iron pipe.




Flashboard Sockets





PLAN OF  
Scale





PLAN OF LOGWAY  
Scale  $\frac{3}{16}'' = 1'-0''$






Max. Flood El. 289.27


Low Water El. 282.07

Flashboard Socket-see detail.



SECTION OF DAM  
Scale: 3/16" = 1'-0"

Made By: [Signature]  
1st Check By: [Signature]  
Designed By: Cosgrave  
2nd Check By: [Signature]



# DOWN-STREAM ELEVATION OF DAM AND HEADGATES

Scales:  $\begin{cases} \text{HOR: } 1" = 50' \\ \text{VERT: } 1" = 20' \end{cases}$


## -NOTES-


All masonry shown on this sheet to be 2nd Class Concrete unless otherwise shown.  
All exposed edges of concrete to be rounded to a radius of  $\frac{1}{4}$  otherwise shown.

Vertical joints not to be spaced over forty (40) feet apart.  
All metal reinforcement to be of deformed bars of minimum size and spacing of bars may be changed slightly provided section of steel remains unchanged.


The bases of the structures shown on any of the plans of considered as approximate only and may be ordered by writing to be at any elevation and of any dimensions not proper foundation.

For details of Bulkheads, see Sheets # 50, 52  
" " " Headgates, " " # 51, 53






DETAIL OF CAP.  
Scale: 3"=1'-0"



Flashboard sockets  
to be 3 1/2" on pipe 2'-0"  
long embedded in  
concrete, spaced about  
4'-0" centers.




DOWN-STREAM  
Scale

unless otherwise shown.  
as of two inches unless

part.  
minimum cross section given.  
provided the total net.


DETAIL OF FLASHBOARD SOCKET.  
Scale 1/2"=1'-0"



def. bars 0.56" net  
area 4'-0" x 12' ctrs

43 def. bars 0.56" net  
32 def. bars 0.56" net

ns of this contract shall be  
red by the State Engineer in  
ns necessary to give a




Front angle at joint to be  
built square and finished  
with a groove.



SECTION A-A

Area of Keyways to be  
between 25% and 40%  
of total area.



SECTION AT END OF FORM  
Scale: 1"=1'-0"

DETAIL OF KEYWAYS


# Contr Champlain Ca

## DETAIL PLAN OF G


Examined and approved

July

Supervising Engineer



DOWN-STREAM ELEVATION OF LOGWAY.  
Scale:  $\frac{3}{16}'' = 1'-0''$



SECTION B-B.  
Scale:  $\frac{3}{16}'' = 1'-0''$

# Contract No. 56.

Implain Canal Section 2

Glens Falls Feeder.

## PLAN OF GLENS FALLS FEEDER DAM



Scales as indicated

approved

Examined and approved

*[Signature]*  
1911  
Engineer

*[Signature]*  
Special Design Engineer





OXIEY P1

Approximate Rock Surface



UP-STREAM ELEVATION

Scale  $\frac{3}{16}$ " = 1'-0"

C100

2

LWEI 20207





EL 204.07

EL 264.07

EL 260.07


21




Drawn by: W. H. H. & Co.  
 Checked by: W. H. H. & Co.  
 Date: 10/1/11  
 Project: W. H. H. & Co.

**NOTES:**

- All masonry shown on this sheet to be 2nd Class Concrete unless otherwise shown.
- All exposed edges of concrete to be rounded to a radius of two inches unless otherwise shown.
- The bases of structures on any of the plans of this contract shall be considered as approximate only, and may be ordered by the State Engineer in writing to be at any elevation and of any dimension necessary to give a proper foundation.
- All metal reinforcement shall be of deformed bars of minimum cross section given. The size and spacing of bars may be changed slightly provided the total net section of steel remains unchanged.
- For detail of road gates, see sheet No. 51.
- For lay-out plan, see sheet No. 49.




**SECTION**  
Scale



**PLAN**


Scale 3/8" = 1'-0"



# Contract Champlain Canal Glens Falls DETAIL PLAN OF GLENS FALLS Scales a

Examined and approved

July 1, 1912  
 G. H. Lickney  
 Supervising Engineer



# Contract No. 56.

ain Canal Section 2

Glens Falls Feeder.

## PLAN OF NORTH BULKHEAD, NS FALLS FEEDER DAM

Scales as indicated

Examined and approved

1912

*John A. Smith*

by

*July 1912*  
*Alfred E. Smith*  
Special Deputy State Engineer

50

2'-0"

10"


4'-0"

6" EX. 4" x 4" x 1/2"


2'-0"

1 5/8"



2'-0"








bolts 2 1/2" lg




1/2" C's & K bolts  
Head to be  
surface of b  
3rd steel w





DETA  
Scale

$\frac{1}{8}$ " C's & bolts 4" lg.  
 Head to be  $\frac{1}{16}$ " below  
 surface of bronze bar  
 3rd steel washers



DETAIL AT "G"

Scale 1 1/2" = 1'-0"




By *W. Hall*  
 Checked by *W. Hall*  
 Drawn by *W. Hall*  
 Project *W. Hall*






be coated after gates are assembled and ready to assemble. Other coats after gates are assembled.

SECTION B-B  
Scale  $\frac{3}{4}" = 1'-0"$



SECTION A-A  
Scale  $\frac{3}{4}" = 1'-0"$



Drilled holes for  $\frac{3}{4}$ "


C. I. BEARR

Scale  $1\frac{1}{2}" = 1'-0"$

Notes.. All material  
other w  
All rivets  $\frac{3}{4}"$   
All holes  $\frac{13}{16}"$   
All exposed

SECTION C-C

Scale  $\frac{3}{4}" = 1'-0"$



Contract


Champlain Canal

95% Fall

DETAILS OF



Drilled holes for  $\frac{3}{4}$ " bronze bolts



**C. I. BEARING**



Scale  $1\frac{1}{2}$ " = 1'-0"

- Notes.. All material medium open hearth steel unless otherwise noted.  
All rivets  $\frac{3}{4}$ " diameter.  
All holes  $\frac{13}{16}$ " diameter unless otherwise noted.  
All exposed faces of bronze to be planed.


**Contract No. 56.**  
**air Cais.** **Section 2**  
**One Falls Feeder.**  
**OF GARDEN NORTH BUNKHEAD**

Scale as indicated


*James H. Smith*  
*Chief Engineer*  
*U.S. Navy*









UP STREAM ELEVATION  
 Scale  $\frac{1}{8}" = 1'-0"$





290.38

El. 290.02

Natural Surface

1 on 3/4 2003

C

El. 274.0

El. 278.0

El. 282.0


4 on 1 Batter

El. 280.0

35'-0"

C


4




Made By: Engr. J. J. J.  
 Checked By: W. J. J.  
 Traced By: P. J. J.  
 2nd Check By: W. J. J.


SECTION B-B  
 Scale: 1" = 10'

Scale  $\frac{1}{8}": 1'-0"$






SECTIONAL ELEVATION



PLAN  
DETAILS FOR ANGLE RECESS  
Scale: 1/2" = 1'-0"



Notes:-  
 All masonry shown on this  
 unless otherwise shown  
 All exposed edges of concrete  
 of two inches unless otherwise shown  
 The bases of structures shown  
 contract shall be considered  
 be ordered by the State Engineer  
 elevation and of any dimensions  
 foundation.  
 For detail of Head Gates  
 For layout plan, see sheet

# Contract D

ALTERATION NO. 1 SHEET

## Champlain Canal

Glens Falls Fe

## DETAIL PLAN OF SOUTH GLENS FALLS F


Scales as indicated

Examined and approved


May 6 1913  
 [Signature]  
 Approving Engineer.

For layout plan, see sheet N° 49

*Special Deputy State*







Technical drawing showing a vertical assembly with dimensions and labels:


- Top label: *inter sunk bolts 2 1/2" long*
- Vertical dimension: *1 L-6" x 3 1/2" x 1" 25'-2" long*
- Horizontal dimension: *1' 8"*
- Horizontal dimension: *8"*
- Horizontal dimension: *3 5/8"*
- Horizontal dimension: *3 1/2" x 1/2"*
- Label: *1/4" Clip L-6" x 6" x 1/2" x 3" long*
- Label: *Holes 1 5/16"*


The drawing shows a vertical plate with several horizontal bolts. A horizontal plate is attached to the side of the vertical plate. The vertical plate is labeled with dimensions and a note about the bolts. The horizontal plate is labeled with dimensions and a note about the clip.


Technical drawing of a ship's hull cross-section showing the connection between the hull and a vertical structural member. The drawing includes two views: a side view on the left and a top view on the right. The side view shows a hull section with a diagonal rib and a vertical member attached. The top view shows the hull section with a vertical member attached, featuring a series of rivets. Labels include "EI 294.5" and "EI 283.5" for the hull sections, and "3" Rivets about 6" Ctr's." for the rivet spacing. A dimension of "5 1/2"" is also shown.

15" I @ 60# - 25'-6" long

$\frac{1}{2}$ "  $\phi$  Countersunk bolts 4" lg.  
 Head to be  $\frac{1}{16}$ " below surface  
 of bronze bar.  
 Standard Steel Washers








Scale:  $\frac{3}{4}$ " = 1'-0"


Diagram showing the elevation of a gate structure. The gate is supported by a sill and a post. Dimensions are indicated in feet and inches:

- Gate width: 4'-11"
- Post width: 5'-2"
- Gate height: 4'-11"
- Gate material: 8" x 12" Y.P. (Yellow Pine)
- Post material: 8" x 12" Y.P. (Yellow Pine)
- Support: 15" I @ 60° - 256 lb.
- Labels: Gate, Bronze bar, Bronze Bolts - 8, Sill, 3 1/2" x 3/4" x 1/2" I.S.

Scale: 2 1/2" = 1' 0"



SECTION C-C.  
Scale  $\frac{3}{4}'' = 1'-0''$



# Contract


## Champlain Canal

Glens Falls

### DETAILS OF GATES

Scales as shown

Examined and approved  
 July 1, 1912  
 S. H. Wiley  
 Supervising Engineer




Contract No. 56.  
 Canal and Plain Canal Section 2  
 Glens Falls Feeder.  
 DETAILS OF GATES, SOUTH BULKHEAD  
 Scales as indicated

Approved


Examined and approved

1912  
 [Signature]  
 Chief Engineer

July 12/12  
 [Signature]  
 Special Deputy State Engineer



*For detail of dam, see sheet \**





EI 294.52

EI 283.52

0.12 YP2

# UP-STREAM ELEVATION

Scale 1/8" = 1'-0"

A ←



2'-6"  
2'-6"  
2'-6"  
2'-6"

EI. 270.0

10'-0"

2'-0"

11 128 2



292.25


El 290.07

Natural Surface


1.00% 510007

C -


El. 274.0	
El 278.0	
El 282.0	
Batter 4 on 1	4



Made By H. W. Benedict  
 Traced By S. P. V. V. V.  
 Checked By W. L. V. V. V. 1912  
 Drawn By W. L. V. V. V.




PLAN  
Scale  $\frac{1}{8}" = 1'-0"$



SECTION A-A

Scale  $\frac{3}{16}" = 1'-0"$



SECTION B-B

Scale  $\frac{3}{16}" = 1'-0"$

July 1, 1912  
G. F. Stebbins  
Supervising Engineer

35'0"

C -

ery shown on this sheet to be 2nd Class Concrete  
is otherwise shown.

edges of concrete to be rounded to a radius of  
inches unless otherwise shown

of structures on any of the plans of this contract  
be considered as approximate only, and may be  
red by the State Engineer in writing to be at any  
tion and of any dimension necessary to give a  
er foundation.

of Head Gates, see sheet No 53

at plan, see sheet No 49

# Contract No. 56.

hamplain Canal

Section 2

Glens Falls Feeder.

## DETAIL PLAN OF SOUTH BULKHEAD, GLENS FALLS FEEDER DAM

Scales as indicated


and approved

Examined and approved

July 1, 1912  
S. J. Decker  
Visiting Engineer

July 1, 1912  
Alfred E. Keith  
Special Deputy State Engineer


52





DETAIL OF ANCHOR BOLT

Scale  $\frac{1}{2}$ " = 1'-0"

16 Required





A



Yellow Pine Str.,  $15' - 9\frac{3}{4}"$  lg










SECTION B-B


Scale: 3/4" = 1'-0"






SECTION B-B  
 $\frac{1}{4}":1'-0"$






DETAIL OF SILL.

Scale:  $\frac{1}{2}$ " = 1'-0"



**BILL OF MATERIAL FOR 1 GRATING**  
 11 bars 3"  $\phi$  - 5' 8" long @ 3.85" per lin. ft.  
 8 bolts 3"  $\phi$  - 5' 8" long @ 5.1" per lin. ft.  
 20 - 8" W.I. Pipe Separators 9" long @ 3.4" per lin. ft.  
 8 - 1/2" rods - 8' 6" long @ 6.0" per lin. ft.  
 2 - 3/8" rods - 8' 10" long @ 1.5" per lin. ft. (Add 0.34" for nuts)  
 20 - 5/8" rivets @ 25.5" per 100"



DETAIL

Sc

Revised By: J. M. Pinner  
 Checked By: J. H. Williams 5-15-12  
 Traced By: J. C. Williams  
 2nd Check By: J. C. Williams 5-15-12

5



El 272.32

El 271.32

FRONT ELEVATION

Scale:  $\frac{1}{16}$  1" = 8'

bars 10° net area  
orig.

El 282.7

to be second class concrete except as noted.  
to be rounded to a radius of two inches unless

formed bars of minimum cross section given.  
bars may be changed slightly provided the total net  
changed.

Nº 13  
second class concrete - classed as Reinforced Concrete.  
13-58-59-60

shown on any of the plans of this contract shall be  
only, and may be ordered by the State Engineer in  
and of any dimensions necessary to give a proper

Contract  
Champlain Canal  
Glens Falls  
DETAILS OF  
Scales

Examined and approved

July 1911  
G. F. Shockey

tra **Contract No. 56.**

Canal Champlain Canal

Glens

S OF

Scales

Glens Falls Feeder.

Section 2

**DETAILS OF BY-PASS, LOCK 14**

Scales as indicated

DATE APPROVED


Examined and approved

*July 1, 1907*  
*G. F. Stokely*  
11 DEC 1907

*July 1, 1907*  
*Alvin E. Haskins*  
Special Deputy State Engineer


26

8




SECTION A-A





EAR


EL. 297



FOREBAY

B

40'-0"



UNIT

4

UNIT #6.



6% 6f



EL 287.5

CABLE TUNNEL

6' STONE  
TOP - EL.

6% GRADE

EL 289.0

A ←

EL 300.0

EARTH FILL

EL 294.0

SLOPE 1 ON 1 1/2

SHEET PILING


APPROXIMATE  
OF EXCAV

APPROXIMATE ORIGINAL R

SEC

DWG. NO.  
FD-11  
FD-11


STONE WALL  
- EL. 287.6 - TO ROCK



OWG. NO.	REFERENCE DRAWINGS	TITLE
FD-11	GENERAL PLAN AND SECTIONS OF POWER HOUSE	
FD-11	EXCAVATION PLAN	

APPROVALS

CHIEF ENGINEER



MOREAU MANUFACTURING CO.

GLENS FALLS N.Y.

FEEDER DAM DEVELOPMENT.

PLAN AND SECTIONS AT  
SOUTH END OF POWER HOUSE.

SCALE:  $\frac{1}{8}$ " = 1'-0"

CHECKED BY:

MADE BY: J. J. K.

DATE: July 17-1922.

FD-18

M

266.0

So

Sc

S

Ch

HUDSON RIVER



NEEDLE DAM SILL

290±


290±

ELEV 290±

ELEV 292±


ELEV 292±

65±







NOTE: THICKNESS OF SILL UNKNOWN



3





4

SKETCH BY J.E.H.  
TRACED BY G.J.R.

TAINTOR GATE

ELEV. 292<sup>+</sup>

ELEV. 290<sup>+</sup>

ELEV. 290<sup>+</sup>

ELEV. 290<sup>+</sup>

ELEV 292±

SLUICE GATE  
7' X 9'

SILL  
ELEV  
279.5±


200'±

ELEV.  
286±


ELEV.  
283±

GLENS

6



7




## SKETCH

SHOWING PLAN AND DOWNSTREAM  
ELEVATION OF THE GLENS FALLS  
FEEDER CANAL INTAKE.

NO SCALE

JULY 1968

8



1+50 W

1+00 W

0+50 W

0+50 E

8+00 N

7+50 N

7+00 N

6+50 N

6+00 N

5+50 N

5+00 N

BASE LINE

CREST AT 54.282

FACE OF EXISTING DAM

R=395.0'

26'-1 1/2"

5.44'

3'-0" 30'-0"

20'-8"

146.0'



1 + 00 E.

305 + 1


 $2 + 00 \text{ E.}$ 


3705 + 3

1000

3 + 50 E.

## HUDSON RIVER P





6 + 00 E

6 + 50 E

7 + 00 E

7 + 50 E

265

266

267


270

275

280


285

4





DATE	NO.
2/2/22	1
2/2/22	2
2/2/22	3
2/2/22	4
2/2/22	5
2/2/22	6
2/2/22	7
2/2/22	8
2/2/22	9
2/2/22	10
2/2/22	11
2/2/22	12
2/2/22	13
2/2/22	14
2/2/22	15
2/2/22	16
2/2/22	17
2/2/22	18
2/2/22	19
2/2/22	20
2/2/22	21
2/2/22	22
2/2/22	23
2/2/22	24
2/2/22	25
2/2/22	26
2/2/22	27
2/2/22	28
2/2/22	29
2/2/22	30
2/2/22	31
2/2/22	32
2/2/22	33
2/2/22	34
2/2/22	35
2/2/22	36
2/2/22	37
2/2/22	38
2/2/22	39
2/2/22	40
2/2/22	41
2/2/22	42
2/2/22	43
2/2/22	44
2/2/22	45
2/2/22	46
2/2/22	47
2/2/22	48
2/2/22	49
2/2/22	50
2/2/22	51
2/2/22	52
2/2/22	53
2/2/22	54
2/2/22	55
2/2/22	56
2/2/22	57
2/2/22	58
2/2/22	59
2/2/22	60
2/2/22	61
2/2/22	62
2/2/22	63
2/2/22	64
2/2/22	65
2/2/22	66
2/2/22	67
2/2/22	68
2/2/22	69
2/2/22	70
2/2/22	71
2/2/22	72
2/2/22	73
2/2/22	74
2/2/22	75
2/2/22	76
2/2/22	77
2/2/22	78
2/2/22	79
2/2/22	80
2/2/22	81
2/2/22	82
2/2/22	83
2/2/22	84
2/2/22	85
2/2/22	86
2/2/22	87
2/2/22	88
2/2/22	89
2/2/22	90
2/2/22	91
2/2/22	92
2/2/22	93
2/2/22	94
2/2/22	95
2/2/22	96
2/2/22	97
2/2/22	98
2/2/22	99
2/2/22	100



MOREA

FEED

PLAN  
FOREBA

SCALE: 1" =

CHECKED B

REFERENCE DRAWINGS

APPROVALS

TITLE

ON THE EXCAVATION FOR FOREBAY

CHIEF ENGINEER



MOREAU MANUFACTURING CO.

GLENS FALLS N.Y.

FEEDER DAM DEVELOPMENT.

PLAN SHOWING EXCAVATION FOR  
FOREBAY, POWER HOUSE AND TAIL RACE.

SCALE: 1" = 30'

8

MADE BY: J. I. K.

CHECKED BY: W.K. 7/13/23

DATE: MAY 22, 1923

15'3"

8- $\frac{3}{4}$ " Deformed Bars 15'0"

BALANCE BEAMS

3'-0"  
1'-0" 1'-0" 1'-0"

$\frac{1}{16}$ " Hole for rod  
to pass through

4 B 3x3x $\frac{3}{8}$ "

2 L 3x4x $\frac{3}{8}$ "

2- $\frac{3}{8}$ " Reinf. Pls.  $\frac{3}{4}$ " Mod Pl.

2 L 3x4x $\frac{3}{8}$ "  
2- $\frac{3}{8}$ " Reinf. Pls.  $\frac{3}{4}$ " Mod Pl.  
plan to bear



2 B 3 1/2" x 3/8" x 17' 3"  
 2 A 5 1/8" x 3/8" x 17' 3"  
 1 C 15" x 3/8" x 17' 3"  
 1 P 1 22" x 3/8" x 17' 3"

17' 3"

THRU BERM  
 Symmetrical about C

4' 5" 6" spaces

8 1/2" 1' 0 1/2"

13' 9 3/4"






8 1/2" 1' 0"

4' 11 3/8"


Babbitt for 1 1/2" Pin

3 3/4"

Drilled Holes for  
 3/4" Turned Bolts Driving in








FRONT ELEVATION DEVELOPED



All material medium O.H. Steel

All rivets  $\frac{3}{4}" \phi$  } unless otherwise noted  
 All holes  $\frac{13}{16}" \phi$  } 4


Scale  $\frac{1}{2}" = 1'-0"$



CONNECTING LINK




ENLARGED DETAIL OF





DNM PLATE & ANGLE  
1 REQUIRED

DESIGNED BY J.C.H.  
 CHECKED BY G. Mesina  
 DATE 6-27-11




ENLARGED SECTION AA

ed hole for 3" Pin  
edge to fl




of Balance Bm. Pin.



Gale Pin


OF BALANCE BM. SUPPLY



ENLARGED END VIEW

One complete





SECTION 66

**Contract No. 56.**

Plain Canal

Section 2

Blaine Falls Reader

**DETAILS OF TANTON RATE**


Section 2 indicated

File 1


100

Examination and Approval

*[Handwritten signature]*







PLAN BB


2


Bearing ABA

Shim

Water seal in  
highest position

Pitch line of rock






MADE BY *J. A. Green* Nov 13, 1913

DESIGNED BY *J. A. Green* " 13

CHECKED BY *C. H. Works* for *W. H. Green*

APPROVED BY *C. H. Mas* *C. H. Mas*



## FRONT ELEVATION


Scale  $\frac{3}{4}" = 1'-0"$

1-Wanted.

All material medium O.H. steel.  
 All rivets  $\frac{5}{8}"$  Holes  $\frac{11}{16}"$  unless other wise noted  
 Painting-Shop coat red lead and oil as  
 per clouse 10s of specifications.

This s  
 accordan

for 1/4 turned bolts  
ring as template



END VIEW

SECTION AA

Sheet is furnished in  
ce with note on sheet 58

Contract

DET  
Champlain Canal  
Glens

DETAILS OF

Scales

Examined and approved  
17 1913  
Superintendent

Scale  $1\frac{1}{2}'' = 1'-0''$

# Contract No. 56.

DETAIL SHEET

Champlain Canal

Glens Falls Feeder

Section 2

## DETAILS OF TANTOR GATE

Scales as indicated


Examined and approved

and approved  
October 17 1913



Superior Engineering

Wm. E. East  
Deputy State Engineer

Operating Hand Wheel













Details of structural supports for Bearings "ABA" will be furnished later.



SECTION B-B.






### LINK BEARING

4 Parts Wanted - Cast Steel

SCALE 3"=1'-0"


DESIGNED BY W. W. W. W.  
 DRAWN BY W. W. W. W.  
 IN CHARGE BY W. W. W. W.  
 CHECK BY W. W. W. W.




### BALANCE BEAM BEARING

2 Wanted - Cast Steel

SCALE 3"=1'-0"




Drilled Holes for  
 $\frac{1}{8}$ " Turned Bolts  
 Driving Fil



MAIN TRUNNION BEARING.

2 Pairs Wanted - Cast Steel.



SCALE 3"=1'-0"




TURNED BOLT FOR LINK BEARING

16 WANTED


SCALE 6"=1'-0"





BALANCE BEAM PIN.  
B-WANTED-C.R. STEEL.  
SCALE 3"-1'-0."




MAIN TRUNNION PIN.  
WANTED - C.R. STEEL.  
SCALE 3"=1'-0."



STEEL BOLT  
SCALE 6"=1'-0"  
1-REQUIRED



WROUGHT IRON KEY  
SMALL KEY SIZE  
2-ACQUIRED




SECTION C-C  
(Bolt Removed)

CAST  
SC  
7

# Contract Champlain Canal Glens Falls DETAILS OF T SAIL

*Wm. H. Hall*



ELEVATION  
CAST IRON LOCK.  
SCALE 6"=1'-0"  
1-REQUIRED.

Contract No. 56.  
 Main Canal Section 2

Glens Falls Feeder.

AR 8 OF TAINTON GATE

Scale as indicated

Examined by

*July 1912*  
*Alfred E. [Signature]*